

Errata Sheet
Suiattle Road 26 Repair Environmental Assessment
May 26, 2006

Page 13 Figure 2: Suiattle Road 26 Repair Map:

Site 2 location is incorrect and map has been corrected to show Site 2 at Downey Creek and is attached.

Page 75, first paragraph under Site #2, last sentence:

“An estimate of the sediment contributed to the Suiattle River is a large flow event....” is corrected to “An estimate of the sediment contributed to the Suiattle River if a large flow event....”

Page 76, Alternative C, Site #1, last paragraph, last sentence:

“The rock pit does not pose any direct sediment delivery risks to nearby streams and only mall amounts of material...” is corrected to “The rock pit does not pose any direct sediment delivery risks to nearby streams and only small amounts of material...”

Page 80, Table 16 Private Land Timber Harvest (last row)

Correct to “yes” for suspended sediment in the Time column, and a “yes” in the cumulative effect column.

Page 85, second paragraph last sentence:

“The repairs would constrict the stream flow under the Downey and Sulphur Bridges due to the approach fills within the bankfull channel width” is deleted from Alternative C. This is the correct statement for Alternative B as shown on page 84.

Page 99, Bat Roost Sites

“Alternatives A, B and” is corrected to “Alternatives A, B and C”.