

Routes Not Probable for Motorized - Summary of Reasons

Clearwater NF Travel Plan

RP-704

WHAT THIS REPORT SHOWS

The report summarizes routes that are coded as Non-Probable motorized routes because they were either:

A) Roads that were not in the Travel Guide because they are overgrown and were not suggested as a motorized route by the public or

B) Trails that were not in the Travel Guide because they are in storage (STO) status and were either not suggested as a motorized trail by the public or did not pass the screening process for suggestions.

During the Travel Plan process these routes were not considered likely to be designated for motorized travel.

<i>Type</i>	<i>Reason for not Probable as Motorized Route</i>	<i>Miles</i>
ROAD		
	Overgrown Not in TG	334
	ROAD	Total
		334
TRAIL		
	Failed Screening	59
	STO Trail / Maint Cost	171
	STO Trail in Wild	17
	TRAIL	Total
		247