

APPENDIX C

Lot Specific Permit Compliance Requirements & Forest Plan (FP) Requirements

Elbow Fork cabin and Firs Recreation Residence Tract

(Items noted were documented in compliance letter, 8/12/2005, sent to all Rec. Residence permittees; or from compliance inspections performed during fall 2006; or during Forest Specialist on site inventories of Summer Home tracts)

Lot #	Description	Repair or Mitigation Requirements
Elbow Fk. 3	Located in Riparian Habit Conservation Area (RHCA), Category 1 (FP). Unauthorized water system.	Remove current unauthorized water withdrawal system as per Forest Service (FS) & Recreation Residence Guidelines (RRG). Cabin owner will work with Salt Lake City Dept. of Public Utilities to determine a source of water, acquire a water agreement and develop a water system that will meet Salt Lake County Health requirements
Firs #1	Located in RHCA, Category 1 (FP). No unauthorized items identified. Vegetation being impacted from cabin use, erosion occurring on access road	Waterbars needed on access road to cabin, trail to the creek and excess parking should be removed and allowed to revert back to native vegetation
2	Located in RHCA, Category 1 (FP). None identified	
3	Located in RHCA, Category 1 (FP). None identified	
4	Located in RHCA, Category 1 (FP). None identified	
5	Located in RHCA, Category 1 (FP). Old outhouse, play or volley ball area	Remove outhouse as per FS & Rec Res guidelines after FS performs historic analysis, restore play/volley ball area to native vegetation
6	Located in RHCA, Category 1 (FP). None identified	
7	Not located in RHCA. (FP). Salt lick block, outhouse used for junk storage, old green swing set not being used, antenna lying on ground	All unauthorized items removed as per FS & Rec Res guidelines, old swing set may belong to lot/cabin #8
8	Located in RHCA, Category 4 (FP). Fence surrounding patio, old swing set mentioned above in #7. Developed seep/spring and water system	All unauthorized items removed as per FS & Rec Res guidelines. Unauthorized spring development and water system and does not meet Salt Lake County Health Standards (RRG)
Firs #9	Located in RHCA, Category 1 (FP). Fence, old electric	All unauthorized items removed as per FS & Rec Res guidelines

	wire to outhouse is attached to trees	
10	Located in RHCA, Category 1 (FP). Chemicals stored outside of cabin (paint, lacquer, etc), hammock bolted to tree	All unauthorized items removed as per FS & Rec Res guidelines
11	Located in RHCA, Category 1 (FP). Metal signpost with no sign	All unauthorized items removed as per FS & Rec Res guidelines
12	Located in RHCA, Category 1 (FP). Shuttle board box game in disrepair, hammock tied to trees	All unauthorized items removed as per FS & Rec Res guidelines,
13	Located in RHCA, Category 1 (FP). None identified	
14	Located in RHCA, Category 1 (FP). Old fire ring structure in disrepair, trash	All unauthorized items removed as per FS & Rec Res guidelines
15	Located in RHCA, Category 1 (FP). None identified	
16	Located in RHCA, Category 1 (FP). None identified	
Firs #17	Located in RHCA, Category 1 (FP). Swing set and sand box in disrepair, concrete pedestal structure near enclosed deck, volleyball area (with poles, lighting, log retention walls, chicken wire netting) has grown in from lack of use	All unauthorized items removed as per FS & Rec Res guidelines, allow volleyball area to return to natural condition after removing items
18	Located in RHCA, Category 1 (FP). Old outhouse structure (may not actually be on this lot), lights in the trees	All unauthorized items removed as per FS & Rec Res guidelines, FS will need to determine which lot the outhouse is located on but is closest to lot #18
19	Located in RHCA, Category 1 (FP). None identified	
20	Located in RHCA, Category 1 (FP). None identified	
21	Located in RHCA, Category 1 (FP). Remove extra old outhouse	Remove outhouse as per FS & Rec Res guidelines after FS performs historic analysis
22	Located in RHCA, Category 1 (FP). Sprinklers tied to trees	All unauthorized items removed as per FS & Rec Res guidelines
23	Located in RHCA, Category 1 (FP). Tether ball pole not in use, old wire strung from shed to outhouse, rock fire ring structure	All unauthorized items removed as per FS & Rec Res guidelines

Firs #24	Located in RHCA, Category 4 (FP). Tire swing connected to tree with a pipe	All unauthorized items removed as per FS & Rec Res guidelines
Firs Track wide	<p>Unauthorized trails leading to the stream</p> <p>Water system, outdoor sprinkler/watering systems, developed spring uphill of Firs lot#8</p> <p>Vegetative treatments</p> <p>Water pollution (sediment), track road system is showing signs of erosion, unnecessary parking areas and trails</p> <p>Water pollution(chemical)</p> <p>Fish passage</p> <p>General maintenance</p> <p>Winter Motorized Access in Mill Creek</p> <p>Play areas, volley ball/basketball areas</p>	<p>*It is reasonable to expect some access to the stream for a cabin owner. Wherever possible this should be existing bridges and trails. All other access routes should be closed and allowed to restore to natural cover. (RRG)</p> <p>* Firs Summer Home Area has their own Water Right, certificate on file identifies for 21 families, however Firs has 24 cabins? Firs has a track wide water system, authorized under permit with the Forest, that meets County and State regulations. Outside sprinkler systems to water vegetation are not allowed.(RRG) Cabins can have an outside water faucet and hose that is available for emergency fire suppression. (RRG)</p> <p>*Approval is required to remove hazard trees in riparian areas. Where possible, hazard trees should be left full length and not cut up into firewood lengths to provide large woody debris and down wood. (FP)</p> <p>Minimize vegetative treatments in RHCA's. (RRG)</p> <p>*Install water bars to reduce runoff velocity. Minimize vegetative treatments in RHCA's. Remove unnecessary parking and trails, cabin owners should allow impacted areas to revert back to native vegetation (RRG)</p> <p>*Convert over time all building materials in RHCA's to non-maintenance type materials, ie., decks should not be chemically treated but converted to materials needing no maintenance.(RRG)</p> <p>*Breakup all man-made rock weirs in Mill Creek stream channel.(RRG)</p> <p>*Remove trash from lots (bricks, blocks, building materials, scrap metal, sand bags, equipment not being used, etc.) (RRG)</p> <p>*As per the Winter Recreation Travel Map, Salt Lake Ranger District, dated 12/15/2005, Mill Creek Canyon is closed to over the snow motorized recreation use and travel on National Forest lands. Use of snowmobile for winter access requires written FS authorization.</p> <p>*Individual cabin play areas should be allowed to revert back to native</p>

