

Chugach National Forest - Hiking (Trailheads) Program Accessibility Transition Plan

Draft 7/14/04

There are 23 developed trailheads on the Chugach National Forest outside of developed campgrounds, picnic grounds, and other day use sites. Each developed/ designated trailhead will include at least one accessible parking space and an Outdoor Recreation Access Route (ORAR) that links parking, signs or bulletin boards, and toilets (if provided) in accordance with the standards in FSORAG¹ as the sites require renovation. Where toilets are provided at trailheads, and as they need to be renovated or replaced, each of them will be reconstructed to comply with ADAAG standards for buildings.

Four of the developed trailheads on the Forest meet current accessibility standards. One more is scheduled for renovation in 2007. Of the remaining 18 developed trailheads, some have accessibility improvements that may include accessible toilets or firm, stable parking areas, or ORARs, but not all three. These trailheads will be improved to full accessibility standards as they require renovation to protect public health and safety or to protect natural resources.

I concur with the strategy outlined in this accessibility transition plan.

Rebecca Nourse

Cordova District Ranger

Jim Fincher

Glacier District Ranger

Debora Cooper

Seward District Ranger

Date

Date

Date

¹ See Introduction for previously defined acronyms.

Geographic Area - Kenai Peninsula

Location	Number of parking spaces	Number of accessible parking spaces	Target number of accessible parking spaces	Obstacles to accessibility target	Planned actions	Year planned	Responsible Official
Byron Glacier Trailhead	20	20	20	None	None	Done	Glacier District Ranger
Carter Lake Trailhead	10	10	10	None	None	Done	Seward District Ranger
Cooper Russian Lake Trailhead	10	0	1	Lack of firm, stable surfacing for parking, and lack of accessible route to bulletin boards and restrooms.	Provide one accessible parking stall and access route to bulletin boards and restrooms as site requires renovation.	As needed	Seward District Ranger
Crescent Creek Trailhead	22	0	2	Lack of firm, stable surfacing for parking, and lack of accessible route to bulletin boards and restrooms.	Provide one accessible parking stall and access route to bulletin boards and restrooms as site requires renovation.	As needed	Seward District Ranger
Crow Pass Trailhead	30	0	3	Lack of accessible parking and access route to bulletin boards and restrooms.	Provide three accessible parking stalls and access route to bulletin boards and restrooms as site requires renovation.	As needed	Glacier District Ranger
Devils Pass Trailhead	20	20	20	Lack of accessible route from parking to restroom.	Provide accessible route from parking to restroom as site requires renovation.	As needed	Seward District Ranger

Geographic Area - Kenai Peninsula

Location	Number of parking spaces	Number of accessible parking spaces	Target number of accessible parking spaces	Obstacles to accessibility target	Planned actions	Year planned	Responsible Official
Grayling Lake Trailhead	10	10	10	None	None	Done	Seward District Ranger
Johnson Pass North Trailhead	20	0	2	Lack of accessible parking.	Provide two accessible parking stalls.	As needed	Glacier District Ranger
Johnson Pass South Trailhead	8	8	8	None	None	Done	Seward District Ranger
Lost Lake Trailhead	10	0	1	Lack of firm, stable surfacing for parking.	Provide one accessible parking stall as site requires renovation.	As needed	Seward District Ranger
Rainbow Lake Trailhead	5	0	1	Lack of accessible parking and access route to bulletin boards and trail.	Provide one accessible parking stall and access route to bulletin boards and trail.	2007	Seward District Ranger
Resurrection Pass North Trailhead	17	0	2	Lack of accessible parking.	Provide two accessible parking stalls.	As needed	Seward District Ranger
Resurrection Pass South Trailhead	17	17	17	Lack of accessible route from parking to bulletin boards and restrooms.	Provide accessible route from parking to bulletin boards and restrooms as site requires renovation.	As needed	Seward District Ranger

Geographic Area - Kenai Peninsula							
Location	Number of parking spaces	Number of accessible parking spaces	Target number of accessible parking spaces	Obstacles to accessibility target	Planned actions	Year planned	Responsible Official
Resurrection River Trailhead	15	0	2	Lack of accessible parking.	Provide two accessible parking stalls.	As needed	Seward District Ranger
Summit Creek Trailhead	6	0	1	Lack of accessible parking and access route to bulletin boards and restrooms.	Provide one accessible parking stall and access route to bulletin boards as site requires renovation.	As needed	Seward District Ranger
Victor Creek Trailhead	2	0	1	Lack of accessible parking and access route to bulletin boards.	Provide one accessible parking stall and access route to bulletin boards as site requires renovation.	As needed	Seward District Ranger

Geographic Area – Prince William Sound							
Location	Number of parking spaces	Number of accessible parking spaces	Target number of accessible parking spaces	Obstacles to accessibility target	Planned actions	Year planned	Responsible Official
None							

Geographic Area – Copper River

Location	Number of parking spaces	Number of accessible parking spaces	Target number of accessible parking spaces	Obstacles to accessibility target	Planned actions	Year planned	Responsible Official
Haystack Trailhead	5	0	1	Lack of accessible parking and access route to bulletin boards.	Provide one accessible parking stall and access route to bulletin boards as site requires renovation.	As needed	Cordova District Ranger
Heney Ridge Trailhead	3	0	1	Lack of accessible parking.	Provide one accessible parking stall.	As needed	Cordova District Ranger
McKinley Lake Trailhead	3	0	1	Lack of accessible parking.	Provide one accessible parking stall.	As needed	Cordova District Ranger
Power Creek Trailhead	3	0	1	Lack of accessible parking and access route to bulletin boards.	Provide one accessible parking stall and access route to bulletin boards as site requires renovation.	As needed	Cordova District Ranger
Saddlebag Glacier Trailhead	3	0	1	Lack of accessible parking and access route to bulletin boards.	Provide one accessible parking stall and access route to bulletin boards as site requires renovation.	As needed	Cordova District Ranger
Sheridan Mountain Trailhead	12	0	2	Lack of accessible parking and access route to bulletin boards.	Provide one accessible parking stall and access route to bulletin boards as site requires renovation.	As needed	Cordova District Ranger

DRAFT