

Lightning Creek Drainage –Effects of the 2006 flood



Lower Lightning Creek in November, 2006 during flood event.



Lower Lightning Creek in July, 2008. Notice dry sections of channel and lack of large wood in floodplain.



Lightning Creek at milepost 13.1 on November 09, 2006.



Lightning Creek at 14.2 milepost on November 09, 2006.




East Fork of Lightning Creek at milepost 1.3 on November 10th, 2006.




Large Cedar trees down in lower East Fork of Lightning Creek.



Debris flow from tributary to Rattle Creek.



Washout of Road #473 near milepost 2.0.



Rattle Creek takes out Road #473




Road #473 washed out at box culvert crossing.



Road #642 bridge to Porcupine Lake.



Damage to Road #642 bridge.



Lower Rattle Creek Road #473 washouts.



Large log jam accumulated in floodplain in upper East Fork of Lightning Creek.




20-foot-high log jam on East Fork of Lightning Creek.



Good fish habitat created by fallen cedar in East Fork of Lightning Creek.



Lightning Creek flowing past Clark Fork, Id.



Lightning Creek and Road #419.