

gis_length

Inside or Outside Project Area	SYSTEM	OPER MAINT	OBJECTIVE MAINT	ROUTE_STAT	Long Term Access	ID	NAME	JURISDICTI	Comment	Commercial Haul Use	Heritage Survey Complete	Known Heritage Site	Pipeline Near Road	Recommended Work Associated with Commerical Haul Route																						
														Maintenance	Not used for haul route	Obliterate	Recondition	Reconstruction	Construction	Grand Total																
inside	NFSR	2	1	EXISTING	YES	44237	(blank)	FS	This is an existing system road. A ROW is on file for the portion	YES	NO	YES	NO						0.31		0.80	0.80														
						44271A	44271A	FS	This is an existing system road. Construction drawings have been	YES	NO	NO	NO													0.31										
						4777B1	4777B1	FS	This is an existing system road. Construction drawings have been	YES	NO	NO	NO															1.20								
						1 Total																												1.20		
						2	2	EXISTING	YES	4027	MARVELL CR RD	FS	No legal access. To project area	NO	NO	NO	NO											0.29								
										40271	(blank)	FS	No legal access. To project area	NO	NO	NO	NO														0.40					
										41337	41337	FS	Not used for haul route.	NO	YES	YES	YES																2.68			
										41338	41338	FS	Not used for haul route.	NO	YES	YES	YES																	6.75		
										41339	41339	FS	Heritage site adjacent to road. Intersection with 4133 needs red	YES	YES	YES	YES																	0.72		
										41339	41339	FS	Herigate site adjacent to road. Steep, bottom of draw, drainage	NO	YES	YES	YES																		0.84	
										4422	OLD WHITETAIL R S	FS	Intersection with 4427 needs reconstructed. Road is a Heritage	YES	YES	YES	NO																		1.71	
										4427	BEAVER PUMPKIN DIVIDE	FS	Heritage sites adjacent to the roadway.	YES	YES	YES	YES																		2.00	
										4427	BEAVER PUMPKIN DIVIDE	FS	Heavy brushing, steep grades, drainage problems.	YES	YES	YES	NO																			2.81
										44271	44271	FS	This is an existing system road. Construction drawings have been	YES	NO	NO	YES																			1.82
										44272	44272	FS	Road is mostly across flat ground. Blading, shaping, and drain	YES	YES	YES	YES																			0.91
		4512	STACEY SPRING	FS	Herigate Site near intersection with 4769. Brushing, blading, sh					YES	YES	YES	YES																			1.08				
		47692	47692	FS	Not used for haul route.					NO	YES	NO	YES																			1.98				
		47692A	47692A	FS	Not used for haul route.					NO	YES	NO	NO																			0.26				
		47696	47696	FS	Intersection with 4169 needs reconstructed.					YES	YES	NO	NO																			0.10				
		2 Total																			2.00	13.21		2.73	6.68	24.61										
		2 Total																			2.00	13.21		4.23	7.48	26.92										
		3	3	EXISTING	YES	4133	BEAVER CR	FS	Heritage - Road not eligible. No foresee problems with this road	YES	YES	YES	NO															0.24								
						4466	WHITETAIL ADMIN. SITE	FS	If commercial use. Maintenance of road will be required. Herig	YES	YES	YES	NO																	0.06						
						4769	BEAVER STACEY	FS	Heavy brushing, drainage problems. Road is recommended eli	NO	YES	YES	NO																		0.16					
						4777	SUICIDE PASS	FS	Maintenance and Surface Rock Replacement.	YES	NO	NO	NO																			3.29				
						4777B	HOLIDAY CAMPGROUND	FS	Route to campground. Maintenance and Surface Rock Replac	YES	YES	YES	NO																			0.98				
						3 Total																			1.46	0.16		3.29	4.92							
						3 Total																			1.46	0.16		3.29	4.92							
		Decom																								0.71										
		1 Total																								0.71										
		Decom Total																								0.71										
		NFSR Total														3.46	13.37		4.23	10.77	32.55															
		COUNTY														1.19					1.19															
		3 Total																			1.19					1.19										
		COUNTY Total																			1.19					1.19										
		UNDETERMINED	(blank)	1	EXISTING	YES	41339A	(blank)	FS	This is an undetermined route. It exists on the ground. What is	YES	NO	NO	NO															0.76							
							44273	44273	FS	This is an undetermined route. It exists on the ground. What is	YES	NO	NO	NO																	0.55					
							1 Total																								1.30					
				2	EXISTING	YES	44235	44235	FS	Keep only a portion of it for dispersed camping after project w	YES	YES	YES	YES																	0.33					
							44237A	(blank)	FS	This is an undetermined route. It exists on the ground. What is	YES	NO	NO	YES																		0.27				
							44271B	44271B	FS	This is an undetermined route. It exists on the ground. Long ter	YES	NO	YES	YES																			0.55			
							47699	47699	FS	This is an undetermined route. It exists on the ground. Long ter	YES	NO	NO	YES																				0.84		
							4777B2	4777B2	FS	This is an undetermined route. It exists on the ground. TMP ha	NO	NO	NO	YES																				0.15		
							2 Total																								0.19					
				Decom																								1.30								
(blank) Total																								1.07												
UNDETERMINED Total																				1.03		1.07	2.60	4.70												
TEMPORARY																				1.03		1.07	2.60	4.70												
TEMPORARY	(blank)			Decom	PLANNED	NO	T1	(blank)	FS	Identified to access harvest units.	YES	NO	NO	NO																0.41						
							T10	(blank)	FS	Identified to access harvest units.	YES	NO	NO	NO																			0.55			
		T11	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																				0.19				
		T12	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																					0.07			
		T13	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																					0.91			
		T14	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																					0.18			
		T15	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																					0.79			
		T16	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																					0.43			
		T17	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																						0.37		
		T18	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																						0.10		
		T2	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																						0.52		
		T3	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																						0.32		
		T4	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																						0.20		
		T5	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																						0.58		
		T6	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																						0.36		
		T7	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																						0.88		
		T8	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																						0.14		
		T9	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																						0.11		
		T19	(blank)				FS	Identified to access harvest units.	YES	NO	NO	NO																						0.25		
		Decom Total																								7.34										
(blank) Total																								7.34												
TEMPORARY Total																			7.34																	
inside Total														4.65	14.40	8.41	6.83	10.77	0.71	45.78																
outside	NFSR	2	1	EXISTING	YES	44237	(blank)	FS	This is an existing system road. A ROW is on file for the portion	YES	NO	YES	NO															0.04								
						1 Total																								0.04						
						2	EXISTING	YES	41338	41338	FS	Heritage site adjacent to road. Intersection with 4133 needs red	YES	YES	YES	YES																		0.23		
		47696	47696	FS	Intersection with 4169 needs reconstructed.				YES	YES	NO	NO																				0.04				
		2 Total																								0.27										
		2 Total																								0.31										
3	3	EXISTING	YES	4133	BEAVER CR	FS	Heritage - Road not eligible. No foresee problems with this road	YES	YES	YES	NO																		1.44							
				4769	BEAVER STACEY	FS	Heavy brushing, drainage problems. Road is recommended eli	YES	YES	YES	NO																				0.23					
				4777	SUICIDE PASS	FS	Maintenance and Surface Rock Replacement.	YES	NO	NO	NO																					0.21				
				3 Total																			1.44					0.23								

gis_length

Inside or Outside Project Area	SYSTEM	OPER MAINT	OBJECTIVE MAINT	ROUTE_STAT	Long Term Access	ID	NAME	JURISDICTI	Comment	Commercial Haul Use	Heritage Survey Complete	Known Heritage Site	Pipeline Near Road	Recommended Work Associated with Commerical Haul Route							
														Maintenance	Not used for haul route	Obliterate	Recondition	Reconstruction	Construction	Grand Total	
outside	NFSR	3	3 Total											1.65				0.23	1.88		
		3 Total													1.65				0.23	1.88	
		Decom	1	DECOMMISSIONED	YES	47696A	47696A	FS	This road was decommissioned in the database. It still exists o	YES	NO	NO	NO						0.20	0.20	
		1 Total																	0.20	0.20	
	Decom Total																		0.20	0.20	
	NFSR Total														1.65				0.54	0.20	2.39
	COUNTY	3	3	EXISTING	YES	4423	E FK OTTER CR	FS	County Maintenance, Schedule A. Collect Surface Rock Replac	YES	YES	YES	NO		3.68					3.68	
		3 Total													7.88					7.88	
		3 Total													11.56					11.56	
	COUNTY Total														11.56					11.56	
UNDETERMINED	(blank)	1	EXISTING	YES	41338A	41338A	FS	No long term need identified in TMP. Obliterate after project wd	YES	NO	NO	NO					0.10		0.10		
	(blank) Total	1 Total															0.10		0.10		
UNDETERMINED Total																		0.10	0.10		
outside Total														13.21				0.10	0.54	0.20	14.05
Grand Total														17.86	14.40	8.41	6.93	11.32	0.91	59.83	