

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
315	3	0.2	Ciruelas Well	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
315	3	0.0	Ciruelas Well	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
315	3	0.2	Ciruelas Well	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
314	3	3.2	Valencia Canyon, Chosa Mesa, Carrizo Canyon, Ahogadero Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
314	3	1.0	Valencia Canyon, Chosa Mesa, Carrizo Canyon, Ahogadero Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
314	3	0.5	Valencia Canyon, Chosa Mesa, Carrizo Canyon, Ahogadero Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
314	3	2.5	Valencia Canyon, Chosa Mesa, Carrizo Canyon, Ahogadero Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
312	3	0.6	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
312	3	0.6	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
311	3	0.0	Cabresto Mesa, La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
311	3	0.7	Cabresto Mesa, La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
310	3	0.0	American Mesa, Ulibarri Canyon, Buzzard Canyon, Dike Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
310	3	0.3	American Mesa, Ulibarri Canyon, Buzzard Canyon, Dike Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
310	3	0.2	American Mesa, Ulibarri Canyon, Buzzard Canyon, Dike Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
310	3	1.6	American Mesa, Ulibarri Canyon, Buzzard Canyon, Dike Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
301	3	1.1	Devils Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
301	3	0.9	Devils Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
218	3	0.3	Carracas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
218	3	3.4	Carracas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
357P1	3	0.1	Fir Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO PAC	3	None noted	1	8	yes
357P	3	0.4	Fir Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO PAC	3	None noted	1	8	yes
357M	3	0.0	Vigas Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
218B2	3	0.1	Sec.13, 32N, 05W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat, Northern Goshawk foraging areas	2	None noted	1	6	yes
218B1A	3	0.1	Sec.13, 32N, 05W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat, Northern Goshawk foraging areas	2	None noted	1	6	yes
218B1	3	0.3	Middle Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat, Northern Goshawk foraging areas	2	None noted	1	6	no

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
218B	3	1.4	Bancos Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
218A	3	0.6	Carracas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	no
218A	3	1.3	Carracas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
218	3	3.5	Carracas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
357M	3	0.2	Vigas Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	6	yes
315G	3	0.3	Ciruelas Well	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
315F	3	0.8	Ciruelas Well	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	6	yes
315E	3	0.0	Cottonwood Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			Sum of Criteria	Min road system
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
314Z	3	0.2	Chosa Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	None noted	1	5	yes
314P	3	0.8	Laguna Seca Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	7	yes
314G	3	0.1	Cedar Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	6	no
314E	3	0.1	Lodge Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	7	yes
314B1	3	0.1	Martinez Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	6	yes
314B	3	0.3	Martinez Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	6	yes
314B	3	0.0	Martinez Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	6	yes
312Q	3	0.1	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	6	yes
312E	3	0.0	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	6	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
312A2	3	0.2	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
312A1A	3	0.1	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
312A1	3	0.8	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	6	yes
312A1	3	0.2	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
312A	3	0.1	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
312A	3	0.5	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
312A	3	1.0	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
311P	3	0.4	Cabresto Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
310A1	3	0.1	Carracas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	None noted	1	5	yes
218C	3	2.2	Carracas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat, Northern Goshawk foraging areas	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	6	no
218B1	3	0.1	Carracas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat this portion of road	1	None noted	1	4	no
218B	3	0.6	Bancos Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat, Northern Goshawk foraging areas	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	6	no
218A1A	3	0.1	Carracas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat, Northern Goshawk foraging areas	1	None noted	1	4	yes
357	3	0.4	Vigas Mesa, Cedar Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
357	3	1.3	Vigas Mesa, Cedar Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
316	3	0.1	Ciruelas Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
315	3	0.7	Ciruelas Well	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
314	3	2.3	Valencia Canyon, Chosa Mesa, Carrizo Canyon, Ahogadero Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
314	3	0.6	Valencia Canyon, Chosa Mesa, Carrizo Canyon, Ahogadero Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
312	3	1.4	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
312	3	0.7	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
312	3	0.5	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
312	3	0.7	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
311	3	0.5	Cabresto Mesa, La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
310	3	1.2	American Mesa, Ulibarri Canyon, Buzzard Canyon, Dike Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
301	3	0.4	Devils Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	6	yes
218	3	0.9	Carracas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
218	3	1.8	Carracas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
218	3	2.3	Carracas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
218	3	0.5	Carracas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Slight Erosion	1	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	4	yes
358B	3	0.3	Tecolote Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
311H	3	0.1	Sec. 23, 30N, 05W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system	
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts			Criteria
311G	3	0.1	Lopez Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
311A	3	0.3	La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	6	yes
309F	3	0.5	La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
309B1	3	0.2	Cabresto Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
309B	3	0.9	Bancos Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
311	3	0.0	Cabresto Mesa, La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
311	3	0.5	Cabresto Mesa, La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
311	3	0.2	Cabresto Mesa, La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
311	3	0.6	Cabresto Mesa, La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
311	3	0.4	Cabresto Mesa, La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
309	3	0.2	Cabresto Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
309	3	0.2	Cabresto Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
358C1	3	0.1	Tecolote Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
358A	3	0.4	Owl Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
357P	3	0.1	Fir Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
316J1	3	0.0	Sec. 33, 27N, 04W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
316J	3	0.3	Sec. 33, 27N, 04W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
316C	3	0.2	Sec. 34, 27N, 04W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
316B	3	0.2	Sec. 34, 27N, 04W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	6	yes
315R	3	0.0	Sec. 22, 27N, 04W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
315N2	3	0.1	Sec. 16, 27N, 04W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	6	yes
315N1	3	0.3	Sec. 21, 27N, 04W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
315N	3	0.5	Sec. 16, 27N, 04W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	6	yes
315K	3	0.5	Sec. 21, 27N, 04W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
315I	3	0.0	Sec. 22, 27N, 04W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
315H2	3	0.1	Sec. 22, 27N, 04W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
315H1	3	0.1	Ciruelas Well	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
315H	3	0.9	Ciruelas Well	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	6	yes
315H	3	0.3	Ciruelas Well	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
315G	3	0.0	Ciruelas Well	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
314F	3	0.4	Oso Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	7	yes
312E	3	0.3	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	7	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
312D	3	0.2	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	7	no
312C1	3	0,0	Manuel Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
312C	3	0,5	Mestenas Peak	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
312A2	3	0,4	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	7	no
312A2	3	0,4	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
312A	3	0,9	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
311T	3	0,1	Cabresto Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	7	yes
311S4	3	0,1	Cabresto Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	7	yes
311S3	3	0,1	Cabresto Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
311S	3	0.3	Cabresto Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
311S	3	0.8	Cabresto Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
311R1	3	0.1	Cabresto Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
311R1	3	0.4	Cabresto Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
311P	3	0.0	Cabresto Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
311O3	3	0.0	Cabresto Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	7	yes
311O2	3	0.2	Cabresto Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	7	yes
311L	3	0.5	Cabresto Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
311K	3	0.1	Sec. 25, 30N, 05W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat and important big game habitat	3	None noted	1	7	yes
311J	3	0.2	Sec. 26, 30N, 05W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	7	yes
310Q	3	0.2	American Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
310P1	3	0.1	American Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
310G	3	0.5	American Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	7	no
310F	3	0.3	American Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	None noted	1	7	yes
310E	3	0.7	American Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
310C1A		0.0	American Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
309B2	3	0.2	Bancos Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
309B	3	1.2	Bancos Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
308B	3	0.2	Bancos Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near Bald Eagle Habitat (winter)	3	None noted	1	7	yes
308B	3	0.6	Bancos Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near Bald Eagle Habitat (winter)	3	None noted	1	7	yes
218B8	3	0.2	Carracas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
218B8	3	0.0	Carracas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
312E1	3	0.3	Chicken Fry Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
358	3	0.0	Tecolote Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
358	3	0.4	Tecolote Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
357	3	0.3	Vigas Mesa, Cedar Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
357	3	0.5	Vigas Mesa, Cedar Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
357	3	0.6	Vigas Mesa, Cedar Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
357	3	0.3	Vigas Mesa, Cedar Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
316	3	1.2	Ciruelas Spring	3 - SUITABLE FOR PASSENGER CARS	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	6	yes
315	3	1.5	Ciruelas Well	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	7	yes
315	3	0.4	Ciruelas Well	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
315	3	0.7	Ciruelas Well	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
312	3	0.1	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
312	3	0.7	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
311	3	1.9	Cabresto Mesa, La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
311	3	1.8	Cabresto Mesa, La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
311	3	1.6	Cabresto Mesa, La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
310	3	0.7	American Mesa, Ulibarri Canyon, Buzzard Canyon, Dike Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
310	3	0.1	American Mesa, Ulibarri Canyon, Buzzard Canyon, Dike Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
310	3	0.2	American Mesa, Ulibarri Canyon, Buzzard Canyon, Dike Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
310	3	2.5	American Mesa, Ulibarri Canyon, Buzzard Canyon, Dike Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
308	3	0.7	West side of Bancos Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	5	yes
305	3	0.2	Sec. 31, 27N, 04W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	6	no
303	3	0.0	Sec. 31, 27N, 04W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Moderate Erosion	2	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	6	no
364D	3	0.7	Vaqueros Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Portions of road within big game habitat and primary winter range	2	None noted	1	7	yes
364A3	3	0.2	La Jara Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	7	no
364A2	3	0.3	Pueblita Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road portion located in or near MSO habitat	3	None noted	1	8	yes

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
364A1	3	0.2	Amarante Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
364A	3	0.9	Pueblita Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road portion located in or near MSO habitat	3	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	9	yes
358A	3	0.2	Owl Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted		5	yes
357Y	3	0.1	Vigas Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
357X	3	0.1	Vigas Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
357W1	3	0.2	Vigas Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	7	yes
357W	3	0.2	Vigas Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
357V	3	0.2	Middle Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
357U	3	0.4	Vigas Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	7	yes
357T	3	0.1	Vigas Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
357AO	3	0.4	Jaramillo Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
357AH	3	0.1	Jaramillo Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	7	no
357AG	3	0.4	Jaramillo Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
357AE	3	0.1	Jaramillo Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
357AD1	3	0.1	Jaramillo Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
357AD	3	0.0	Jaramillo Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system	
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts			Criteria
357AC	3	0.3	Jaramillo Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
357AB	3	0.4	Jaramillo Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
357AA	3	0.1	Jaramillo Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
316K	3	0.0	Sec. 33, 27N, 04W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
315P	3	0.5	Ciruelas Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
314AP1	3	0.2	Carrizo Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
314AP	3	0.5	Carrizo Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
314AN	3	0.4	Willow Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Big Game habitat and primary winter range	2	None noted	1	7	yes

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
314AI	3	0.5	Ahogadero Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Big Game habitat and primary winter range	2	None noted	1	7	yes
314AH	3	0.1	Ahogadero Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Big Game habitat and primary winter range	2	None noted	1	7	yes
314AD	3	0.2	Ahogadero Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Big Game habitat and primary winter range	2	None noted	1	7	yes
314AC	3	0.2	Ahogadero Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Big Game habitat and primary winter range	2	None noted	1	7	yes
314A	3	1.8	Carrizo Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Big Game habitat and primary winter range	2	None noted	1	7	yes
312M	3	0.1	Manuel Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
312L1	3	0.0	Manuel Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
312L	3	1.8	Manuel Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
312H	3	0.7	Manuel Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	Road located in or near MSO critical habitat	3	None noted	1	8	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
312G	3	0.1	Mestenas Peak	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
312C1	3	1.2	Manuel Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	7	no
311G	3	0.2	Lopez Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes
311E	3	0.4	Lopez Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes
311D	3	0.3	La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
311C1B	3	0.0	La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
311C	3	1.0	La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
311B1	3	0.2	La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes
311B	3	0.2	La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
311A	3	0.2	La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
310O	3	0.5	Cabresto Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	3	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	9	yes
310L	3	1.5	Ruben Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	None noted	1	7	yes
310J2	3	1.3	Espinosa Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	None noted	1	7	yes
310J	3	2.4	Maestas Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
310J	3	0.6	Maestas Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes
310D2	3	0.2	Chicosa Ridge	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	None noted	1	7	yes
310D1	3	3.1	Chicosa Ridge	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	None noted	1	7	yes
310D	3	5.5	Chicosa Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
310C1A	3	0.3	Estufa Ridge	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	7	no
310B	3	0.0	Buzzard Park	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
309K	3	0.1	Sec. 28, 31N, 05W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	None noted	1	7	yes
309H	3	0.1	Laguna Seca Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	None noted	1	7	yes
309G	3	0.2	Cabresto Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
309F	3	0.4	La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	None noted	1	7	yes
309E	3	1.1	Cabrero Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	7	yes
309C	3	1.4	Cat Draw	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
309B2	3	0.1	Bancos Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat		None noted	1	5	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
309B1	3	0.2	Cabresto Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	None noted	1	7	yes
309B	3	0.8	Bancos Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	no
309B	3	0.7	Bancos Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
309B	3	0.5	Bancos Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
308B	3	0.2	Bancos Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near Bald Eagle Habitat (winter)	3	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	9	no
308A	3	0.3	Bancos Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near Bald Eagle Habitat (winter)	3	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	9	yes
301A1	3	0.3	Vaqueros	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	None noted	1	7	yes
301A	3	0.2	Vaqueros	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system	
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts			Criteria
300B	3	0.0	Munez Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
218B8	3	0.8	West side of Bancos Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	None noted	1	7	yes
218A	3	0.3	Carracas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
311E1	3	0.2	Lopez Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	None noted	1	7	yes
309E1	3	0.2	Cabrero Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	7	yes
358	3	0.3	Tecolote Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO PAC	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
358	3	0.9	Tecolote Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
357	3	2.1	Vigas Mesa, Cedar Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
357	3	2.2	Vigas Mesa, Cedar Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
318	3	0.1	Cabresto Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	See Specific Sheets	3	None noted	1	8	yes
314	3	4.6	Valencia Canyon, Chosa Mesa, Carrizo Canyon, Ahogadero Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
312	3	0.1	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near MSO critical habitat	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
312	3	0.5	Mestenas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
311	3	2.2	Cabresto Mesa, La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
311	3	0.3	Cabresto Mesa, La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
311	3	0.5	Cabresto Mesa, La Fragua Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria
310	3	1.8	American Mesa, Ulibarri Canyon, Buzzard Canyon, Dike Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	5	yes
310	3	3.1	American Mesa, Ulibarri Canyon, Buzzard Canyon, Dike Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	6	yes
310	3	2.0	American Mesa, Ulibarri Canyon, Buzzard Canyon, Dike Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	6	yes
309	3	3.6	Cabresto Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	6	yes
309	3	0.7	Cabresto Canyon	3 - SUITABLE FOR PASSENGER CARS	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	8	yes
308	3	1.1	West side of Bancos Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	None noted	7	yes
306	3	0.3	Sec. 7, 27N, 04W	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	6	yes
218	3	0.1	Carracas Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	6	yes

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
357T1	3	0.1	Vigas Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	7	yes
357T	3	0.6	Vigas Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
357I	3	0.0	Gas Buggy	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
357G	3	0.7	Leandro Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes
357AX	3	1.0	Laguna Seca Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes
315E	3	0.2	Cottonwood Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes
315C	3	0.2	Cottonwood Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes
314T	3	0.5	Valencia Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes
314R	3	0.1	Valencia Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
314N4	3	0.5	Lake Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes
314N	3	0.7	Lake Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
314M	3	0.9	Lake Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes
314AS	3	0.4	Cottonwood Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes
314AM3	3	0.2	Cottonwood Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes
314AM2	3	0.2	Cottonwood Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes
314AM1	3	0.2	Cottonwood Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	no
314AM	3	0.5	Cottonwood Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near big game habitat and primary winter range	2	None noted	1	7	yes
301B	3	0.1	Devils Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	None noted	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
357	3	0.1	Vigas Mesa, Vigas Canyon, Jaramillo Canyon	3 - SUITABLE FOR PASSENGER CARS	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	Road located in or near MSO PAC	3	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	9	yes
357	3	2.1	Vigas Mesa, Cedar Spring	3 - SUITABLE FOR PASSENGER CARS	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	Road located in or near MSO PAC	3	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	9	yes
314	3	0.8	Valencia Canyon, Chosa Mesa, Carrizo Canyon, Ahogadero Canyon	3 - SUITABLE FOR PASSENGER CARS	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	Open road use and specialized wildlife habitat	Road located in or near important big game habitat	2	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	8	yes
314	3	1.5	Valencia Canyon, Chosa Mesa, Carrizo Canyon, Ahogadero Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	None noted	No special concerns such as MSO habitat, Northern Goshawk nest sites or Post Fledging areas, big game winter habitat	1	None noted	1	6	yes
310	3	0.0	American Mesa, Ulibarri Canyon, Buzzard Canyon, Dike Canyon	3 - SUITABLE FOR PASSENGER CARS	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road along ridge top/crosses into three watersheds	1	Open road use and specialized wildlife habitat	See Specific Sheets	3	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	9	yes
218	3	0.2	Carracas Mesa	3 - SUITABLE FOR PASSENGER CARS	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	IMP - IMPROVED NATIVE MATERIAL	yes	Severe Erosion	3	None noted	Road crosses into two watersheds	1	Open road use and specialized wildlife habitat	See Specific Sheets	3	Cultural resources known to be present adjacent to or near the road location. Location is not public information per Antiquities Act and others	2	9	yes
5	4	2.1	La Jara	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	AGG - CRUSHED AGGREGATE OR GRAVEL	yes	Yes, however will be mitigated w/La Jara decision Sloppy w/Mud, Ruts, Poorly Drained, Plugged Culverts Speed & Road Condition	3	Yes, however will be mitigated w/La Jara decision memo	Yes, however will be mitigated w/La Jara decision memo	2	Elk Wintering Range, Cutthroat Trout	Maintain winter seasonal closure and decrease sedimentation.	3	Recreation/ Range		8	yes
10	4	2.40	Shadow Mountain	3 - SUITABLE FOR PASSENGER CARS	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	AGG - CRUSHED AGGREGATE OR GRAVEL	None noted	None noted Hard surface/ gravel, culvert(s)	1	Yes	Potential sedimentation into creek - Capulin.	2	No	None	1	Recreation, FIRE, Timber products		4	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
17	4	4.00	East Fork	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	steep grade, erodible, no engineering native, big mess, Zero mntnc, neglected	3	yes	silting and sediment into e. fork Luna Cr- cutthroat	3	Yes	cutthroat established road has some stream crossing,	3	minimal dispersed rec use, wood poaching, timber products, Access to FR 76	9	yes	
29	4	4.6	Ojo sarco	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	C - COLLECTOR	AGG - CRUSHED AGGREGATE OR GRAVEL	yes	SO HELP BC PRIVATE LAND ISSUES	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no	
70	4	5.4	valle escondito	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NATIVE AND GRAVEL	Yes	rutting near gate to Valle Largo and 0.9 miles up Hard surface/ gravel, culvert(s)	2	no	poss on private land	1	yes	maintain closure to full size vehicles for wildlife calving	2	Timber products, access to motorized trail 70 no change in trail designation leave existing trail open limit to 50 inches or less 5950 meters/3.7 miles	5	yes	
76	4	9.7	Angel fire/la junta	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	A - ARTERIAL	AGG - CRUSHED AGGREGATE OR GRAVEL	yes	from Little Korea to Black Lk, eroding, rutting mixed: gravel from 518 to little korea, then native/mixed to black lake, rutting of road	2	yes	culverts needed for tribes; multiple watersheds affected, sedimentation into La Presa acequia	2	yes	bears with recreation	2	yes: range- cows and people, timber products, Arizona Willow in Little Korea	6	yes	
89	4	0.8	Scout Camp	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	AGG - CRUSHED AGGREGATE OR GRAVEL	yes	crosses Rio Pueblo, needs to be watched for watershed issues cobbly, boulders, native, moonscape	1	poss	crosses Rio Pueblo, atv use?	2	yes	cutthroats with sedimentation	2	range- part of angostora/knob allotment, no real issues. Rec- hun ting access, BSA camp, one of few legal motorized routes, unauthorized trail construction by adjacent private landowners (Loma Linda)	5	no	
114	4	7.0	Picuris lookout/US Hill vista	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	yes	
116	4	6.5	Santa Barbara	5 - HIGH DEGREE OF USER COMFORT	4 - MODERATE DEGREE OF USER COMFORT	C - COLLECTOR	AGG - CRUSHED AGGREGATE OR GRAVEL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	yes	
153	4	6.0	Rito de Olla	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	C - COLLECTOR	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	yes	
155	4	4.8	Truchas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	yes	
156	4	6.5	Truchas west 76/ Jacinto	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	YES	
157	4	4.7	Truchas/ La Joya	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	C - COLLECTOR	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no	
160	4	4.2	Chamisal Canyon/Ojito	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	yes	

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system	
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts			Criteria
161	4	4.2	Serpent Lake trailhead	4 - MODERATE DEGREE OF USER COMFORT	4 - MODERATE DEGREE OF USER COMFORT	C - COLLECTOR	AGG - CRUSHED AGGREGATE OR GRAVEL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	fuelwood collection		3	yes
207	4	8.3	trampas	4 - MODERATE DEGREE OF USER COMFORT	3 - SUITABLE FOR PASSENGER CARS	L - LOCAL	AGG - CRUSHED AGGREGATE OR GRAVEL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	yes
437	4	21.0	Rio chiquito	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	C - COLLECTOR	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	yes
438	4	5.6	Garcia Park/bernadin lake	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	C - COLLECTOR	NAT - NATIVE MATERIAL	yes	erosion due to natural processes	2	yes	sedimentation, trash, pollution into streams	2	yes	degradation of riparian by campers	2	yes; sawmill site-provides access to deer park for wildlife poachers; provides access to archeology sites/pothunting; noxious weed vector		6	yes part of road washed out fishing areas, hiking, camping, mountain biking change access to trail leave one mile open close 6 miles in canyon
439	4	11.6	Little Rio Grande	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	C - COLLECTOR	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	yes
440	4	10.6	Maestas Ridge	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	C - COLLECTOR	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	yes
441	4	12.6	Bear Wallow	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	high arch site density potential impacts from motorized use;		3	yes
442	4	16.0	US Hill	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	C - COLLECTOR	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	yes
468	4	1.1	Borrego Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	poor soils slippery when wet	2	Yes	Watershed issues addressed in 04 veg anaysis/DM	2	None noted	None noted	1	None noted		5	no
469	4	3.4	telephone canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	Yes	eroded, sedimentation into creek	2	ditch needs culvert	Ditch access needed, ditch maintenance needed, off-site sedimentation	2	None noted	None noted	1	heritage concerns in Osha Canyon (Camino Real Rd)		5	yes
476	4	2.8	Vallecitos	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L-LOCAL	NAT-NATIVE MATERIAL	Upper Portion	Upper portion is eroded	2	erosion	erosion from land grant boundary to riparian area	2	None noted	None noted	1	None noted		5	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
478	4	4.2	Rio Chiquito North/S&H Road	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	Yes	erosion entire length	2		Steep, inadequate drainage, eroded	2	yes	poaching is occurring	2	timber theft - latillas		6	yes
606	4	2.1	Hondo Canyon/Horse shoe Curve	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	Yes	erodes into Arroyo Hondo	2	Yes	erosion into Arroyo Hondo, road crosses creek and is in creek, road width narrowed due to erosion	3	None noted	None noted	1	being used as dump site, needs coordination with BLM		6	no
639 section south	4	3.6	Trampas trailhead to Truchas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	Yes	Most culverts washed out or damaged	2	Yes	sediment into Rio de Las Trampas, road goes through river	2	yes	cutthroat established road some stream crossings	2	None noted		6	yes
639 section north	4	3.6	Alamo/dinner section	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL		mud holes, maint. issues	2	Yes	sediment into Rio chiquito,	2	yes	cutthroat established road some stream crossings	2	None noted		6	yes
667	4	4.4	Truchas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	washed out, adjacent to Rio Truchas, sandstone	3	None noted	None noted	1	yes	Rio Grande Cutthroat adjacent to road	3	None noted		7	no
668	4	5.1	cebadilla canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT-NATIVE MATERIAL	yes	drainage problems, sandy slope	2	None noted	None noted	1	yes	possible sensitive species	3	None noted		6	yes
697	4	5.2	West Entranas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT-NATIVE MATERIAL	yes	greasy when wet, dusty when dry	2	None noted	None noted	1	None noted	None noted	1	cultural resource concerns		4	yes
702	4	0.6	Hodges	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT-NATIVE MATERIAL	yes	can't stabilize adjacent ditch	2	yes	ditch and river border road, often washed out	3	yes	cutthroat and exotics in stream	2	narrow road one lane no room to maneuver		7	no
703	4	0.7	Amole Canyon	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	L - LOCAL	AGG - CRUSHED AGGREGATE OR GRAVEL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	yes
705	4	1.7	Apache pass	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	access to private lands, access to NF lands US 64 through pvt land open after pvt land close		3	no
706	4	0.7	Ok Corral/La Jara	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT-NATIVE MATERIAL	yes	Rutted, eroded is addressed in La Jara WUI decision	2	see La Jara WUI decision	see La Jara WUI decision	2	None noted	None noted	1	Heavy dispersed area use		5	no
708	4	0.8	Agua Piedra camp	5 - SUITABLE FOR PASSENGER CARS, HIGH DEGREE OF COMFORT	5 - SUITABLE FOR PASSENGER CARS, HIGH DEGREE OF COMFORT	L - LOCAL	Paved	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
710	4	3.7	Truchas/Ojo Sarco	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	Yes	Erosion, sedimentation	2	None noted	None noted	1	None noted	None noted	1	None noted		4	no
714	4	12.6	Alamos Canyon	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	C - COLLECTOR	NAT-NATIVE MATERIAL	yes	erosion, sedimentation	2	None noted	None noted	1	None noted	None noted	1	None noted		4	no
716	4	5.0	Osha cienega	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system	
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts			Criteria
720	4	6.0	Warm Springs	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	Road closed as per Warm Springs TS. 1/24/07; heritage.		3	no
722	4	6.3	Cerro Pichaco/Romeo Lakes	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	yes	wildlife poaching	2	dispersed camping hunting popular, product poaching		4	yes
723	4	2.3	Holman Hill	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	AGG - CRUSHED AGGREGATE OR GRAVEL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	heritage		3	no
740	4	1.8	Osha Cienea	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	AGG - CRUSHED AGGREGATE OR GRAVEL	yes	erosion	2	yes	spring at head of road	1	None noted	None noted	1	None noted		4	no
745	4	1.5	Ruedas/Truchas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	ridge top	1	None noted	ridgetop	1	None noted	None noted	1	None noted		3	no
76E1	4	1.7	Little Korea	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	connects trail 12 to 76		3	no
1874	4	2.0	Sardinas Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	adjacent to creek needs culverts	2	yes	adjacent to creek needs culverts	2	yes	cutthroat stream	2	becomes trail 12 motorized trail to 76E1 designated as motorized trail		6	no
1877	4	4.0	Bear Mountain	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	steep and rutted	2	yes	sedimentation, roads in creek below lagunitas	2	yes	poaching	2	green fuelwood		6	no
1889	4	3.1	Arellano	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	AGG - CRUSHED AGGREGATE OR GRAVEL	yes	rutted	2	yes	sedimentation into sardinas	2	None noted	None noted	1	fuelwood		5	no
10A	4	1.8	Monistary shadow mtn	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	AGG - CRUSHED AGGREGATE OR GRAVEL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	Timber sale in progress		3	yes
10A1	4	2.8	Capulin Timber Sale and beyond	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	Timber sale using this now		3	no
10A10	4	0.2	Capulin	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	private land access; access to motorized trail #494 which has SUP users		3	no
10A2	4	2.3	Piedras canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	rutted closed road not maintained	2	yes	closed road not maintained	1	yes	poaching	2	None noted		5	no
10AA	4	1.7	Capulin Canyon	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	rutted closed road not maintained	1	yes	closed road not maintained	1	yes	poaching	1	None noted		3	no
153A	4	2.1	Bernadin Lake	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	closed road not maintained	1	yes	closed road not maintained	1	yes	cutthroat in frijoles; elk calving	1	None noted		3	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
155E	4	0.2	Ruedas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	future product sale		3	no
155T2	4	0.8	Ruedas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
155T3	4	1.3	montes/truchas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	road is closed currently not on existing system 1/24/07		3	no
155T4	4	0.8	Ruedas/Truchas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
155T5	4	0.9	Ruedas/Truchas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
155T7	4	2.3	Montes Vigil	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	road closed		3	no
156J	4	1.6	Entranas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	in sandy bottom	1	yes	in sandy bottom	1	None noted	None noted	1	range access needs		3	no
156K	4	4.3	cejita	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	low use		3	no
157T1	4	1.6	La Joya	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
157T2	4	1.3	Ojo Sarco	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
157T3	4	0.8	Alamos canyon	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	closed roads access this road removed from system on 1/24/07		3	no
161D	4	3.2	agua fria	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	eroded near bridge	2	yes	sedimentation into alamitos	2	yes	cutthroat in Alamitos	2	road open to bridge ATV cross drainage and access Santa Fe N change length of open road to 380 meters/2 miles remainder of road is closed		6	no
17T1	4	0.3	Cerro Vista	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
17T2	4	0.7	East Fork	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	road is closed not on existing system		3	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
1889A	4	1.3	above La Junta summer homes	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	connect proposed motorized trails		3	no
1889A1	4	1.0	La Junta homes	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	rec residences, trailhead		3	no
1889B	4	2.4	La Junta Summer homes	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	connect proposed motorized trails		3	no
29A	4	3.3	ojo sarco/dixon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	Sandy wash in intermittent stream	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
29B	4	1.9	Ojo Sarco/dixon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	Sandy wash in intermittent stream	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
29B1	4	2.6	Ojo Sarco/dixon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
29C	4	1.0	Ojo Sarco/Vallecito	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
437A	4	2.5	Valle escondido	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	after Tecolote spring it goes up steep	1	yes	after tecolote spring it goes up into the steeps	1	None noted	None noted	1	None noted		3	no
437B	4	1.4	Valle escondido	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
437C	4	0.6	Valle escondido	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	Native	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
437CG	4	1.1	Mexican canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
437D	4	1.0	Valle escondido	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
437E	4	1.1	Valle Escondido	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
439A	4	1.9	Maestas Ridge	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	C - COLLECTOR	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	yes
439AB	4	1.5	maestas/diablo	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
439AC	4	2.0	Maestas Ridge	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	mess of roads intersecting	1	yes	mess of roads intersecting	1	None noted	None noted	1	None noted		3	no
439AE	4	2.9	Maestas ridge/cerro vista	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	mess of roads intersecting	1	yes	mess of roads intersecting	1	None noted	None noted	1	None noted		3	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
440AA	4	2.3	Maestas/ 2 sections 1canyon Ojito, 2 Bilbao	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	mess of roads intersecting	1	yes	crosses lots of streams	3	None noted	None noted	1	None noted	5	no	
440B	4	2.7	Maestas Park	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no	
440I	4	3.9	MaestasRidge	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no	
440L	4	0.8	maestas Park	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no	
440M	4	Park	Maestas Park	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no	
440MA	4	2.3	Maestas Park	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no	
468A	4	0.9	mica mine road	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	AGG - CRUSHED AGGREGATE OR GRAVEL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	access private lands old mica mine now owned by Picuris Pueblo	3	no	
5A	4	1.3	La Jara	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no	
606B	4	0.4	Hondo canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	old spur off 606	3	no	
639AT1	4	0.2	Ojito to LLano	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	community access Ojito to Penasco	3	no	
639AT2	4	0.6	Penasco	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no	
639B	4	4.1	Santa Barbara/Diner	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	green fuelwood road	3	no	
639T1	4	0.8	Tafoya ranch	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	yes	Rio Grande Cutthroats	3	None noted	5	no	
639T12	4	0.6	Trampas trailhead	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	green fuelwood/ hunt access to atv use area	3	no	
639T12A	4	0.5	Trampas Trailhead	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	steep	1	yes	steep	1	None noted	None noted	1	continuation of 639T12	3	no	
639T3	4	1.3	Truchas area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no	

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
639T4	4	1.9	trampass	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
668A	4	4.7	alamo dinner	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
668AT1	4	1.3	Between Ojito and Rio Chiquito	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
668AT3	4	1.3	Between Ojito and Rio Chiquito	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
668AT5	4	1.2	Between Ojito and Rio Chiquito	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	continuation of 668aaccess from Penasco		3	no
668AT8	4	1.0	Between Ojito and Rio Chiquito	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
668T4	4	2.5	Between Ojito and Rio Chiquito	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
668T5	4	0.6	Between Ojito and Rio Chiquito	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
668T6	4	0.6	Between Ojito and Rio Chiquito	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
668T7	4	1.2	Between Ojito and Rio Chiquito	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
697G	4	1.0	Entranass	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
697H	4	1.0	Entranass	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
697J	4	0.6	Entranass	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
697K	4	1.4	Entranass	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
703B	4	1.4	Amole canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	None noted	2	yes	several meadows requiring protection	2	yes	poaching	2	None noted		6	no
706A	4	5.0	Taos Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
706A1	4	1.0	La Jara area	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
70A	4	2.3	Tienditas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	AGG - CRUSHED AGGREGATE OR GRAVEL	no	soil erosion has become a drainage	3	yes	has become drainage, sediment not creek tht crosses	3	None noted	None noted	1	access to private lands, rec use, range permittee		7	no
710T1	4	1.1	Truchas/Ojo Sarco	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	erosion and sedimentation	2	yes	road is adjacent to drainage	2	None noted	None noted	1	None noted		5	no
714A	4	1.1	trampas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	road is closed on the ground		3	no
714B	4	0.9	trampas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	road is closed on the ground deleted from system 1/24/07		3	no
714T3	4	0.5	Ojo sarco	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no
720A	4	1.2	Warm springs	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	Possible	soils on steep slopes,	1	None noted	None noted	1	Yes	secure area for large game	2	heritage resources concerns, adjacent to Picuris Pueblo Warm Springs TS closed this road		4	no
720B	4	1.7	Warm Springs	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	Possible	soils on steep slopes,	1	None noted	None noted	1	Yes	secure area for large game	2	road was listed as closed in Warm Springs TS updated 1/24/07		4	no
720C	4	1.6	Warm Springs	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	Possible	soils on steep slopes,	2	None noted	None noted	1	Yes	secure area for large game	2	road closed in Warm Springs TS. Removed from system 1/24/07		5	no
720D	4	1.0	Warm Springs	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	Possible	soils on steep slopes,	2	None noted	None noted	1	Yes	secure area for large game	2	road closed in Warm Springs TS. Removed from system 1/24/07		5	no
720D1	4	1.2	Warm springs	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	Possible	soils on steep slopes,	2	None noted	None noted	1	Yes	secure area for large game	2	road is closed as per Warm Spring TS. Removed from the existing open system		5	no
720D2	4	0.6	Warm springs	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	Possible	soils on steep slopes,	2	None noted	None noted	1	Yes	secure area for large game	2	needs to be changed in infra to level 1 Not on existing system		5	no
722A	4	1.1	Loring spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	yes	illegal vehicles are impacting meadow	2	None noted	None noted	1	range, wildlife,		4	no
722B	4	1.3	angostura /agua sarca	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	trail 16 motorized trail pull out		3	no
723A	4	0.6	Holman Hill	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	cemetery access		3	no
743T1	4	3.5	El Valle/ vallecitos south	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	acequia access ?		3	no
743T2	4	2.3	El Valle/ vallecitos south	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	acequia access ? Private land adjacent		3	no
76B1	4	2.1	Chamisal/ Canada de La Madera	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted		3	no

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts		
76BB	4	1.1	Chamisal/transfer station	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no
76E	4	4.1	Little Korea	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	yes	RGCT rito la presa	3	recreation dispersed camping sites,	5	no
76ET2	4	0.8	La Joya	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no
76ET3	4	0.9	La Joya fuelwood road	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no
76F	4	4.5	Quemado	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no
76F1	4	0.5	Quemado	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	acequia access	3	no
76F2	4	1.8	Quemado	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no
76F3	4	1.0	Quemado	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	road density	1			1	yes	wildlife security	1	None noted	3	no
76F4	4	0.9	Quemado	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no
76F4A	4	0.7	Quemado	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no
76G	4	1.0	little Korea	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	deadends removed from system as per district 1/24/07	3	no
76G1	4	1.4	little Korea	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	steep sidehill	1	yes	crosses few streams	1	None noted	None noted	1	removed from existing system as per district road is closed 1/24/07	3	no
76HT1	4	1.1	Ruedas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	in gully	2	yes	in gully	2	None noted	None noted	1	None noted	5	no
76IT1	4	0.80	Ruedas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	in gully	2	yes	in gully	2	None noted	None noted	1	None noted	5	no
76J	4	0.20	Jarosa Creek	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	connects to 76 L approximate length 5600 meters/3.4 miles for use as ATV motorcycle use trail	3	no
76JT1	4	1.50	Ruedas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	road is closed remove from existing system 1/24/07	3	no
76KKT1	4	1.20	Ruedas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts		
76L	4	0.53	Black Lake	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	add closed portion as motorized trail. Will add 4500 meters/2.7 miles to system of motorized trails currently being used by motorcycles and atvs	3	no
76l extens	4		Manuel Romero trail	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	no
76M1	4	1.4	Truchas/ Canada Abeyta	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	entrada en BLM	3	no
76N	4	0.5	Bull Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	steep. Erosion	1	yes	erosion	2	None noted	None noted	1	range	4	no
76NN	4	0.8	Canada Ancha	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	NAT - NATIVE MATERIAL	yes	erosion	1	yes	erosion	2	None noted	None noted	1	None noted	4	no
89A	4	0.1	scout camp	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	L - LOCAL	Native	None noted	None noted	1	Possible	road is bad shape poor condition	2	None noted	None noted	1	None noted	4	no
494	4	6.3	Capulin /shadow mountain	1 - BASIC CUSTODIAL CARE (CLOSED)	1 - BASIC CUSTODIAL CARE (CLOSED)	L - LOCAL	Native	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	yes
70	4	5.4	Valle Largo	1 - BASIC CUSTODIAL CARE (CLOSED)	1 - BASIC CUSTODIAL CARE (CLOSED)	L - LOCAL	Native	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	yes
12	4	4.6	Sardinas canyon	1 - BASIC CUSTODIAL CARE (CLOSED)	1 - BASIC CUSTODIAL CARE (CLOSED)	L - LOCAL	Native	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	yes
13	4	4.2	Policarpio	1 - BASIC CUSTODIAL CARE (CLOSED)	1 - BASIC CUSTODIAL CARE (CLOSED)	L - LOCAL	Native	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	yes other values to keep
8	4	3.2	La Cueva	1 - BASIC CUSTODIAL CARE (CLOSED)	1 - BASIC CUSTODIAL CARE (CLOSED)	L - LOCAL	Native	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	yes
182	4	7.5	Gallegos Peak	1 - BASIC CUSTODIAL CARE (CLOSED)	1 - BASIC CUSTODIAL CARE (CLOSED)	L - LOCAL	Native	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	yes other values motorcycles
492	4	5.0	La Cueva canyon	1 - BASIC CUSTODIAL CARE (CLOSED)	1 - BASIC CUSTODIAL CARE (CLOSED)	L - LOCAL	Native	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	yes
4	4	3.1	Gallegos Canyon	1 - BASIC CUSTODIAL CARE (CLOSED)	1 - BASIC CUSTODIAL CARE (CLOSED)	L - LOCAL	Native	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	yes
5	4	4.5	Canon Tio Maes	1 - BASIC CUSTODIAL CARE (CLOSED)	1 - BASIC CUSTODIAL CARE (CLOSED)	L - LOCAL	Native	None noted	None noted	1	None noted	None noted	1	None noted	None noted	1	None noted	3	yes
22	4	6.0	Comales	1 - BASIC CUSTODIAL CARE (CLOSED)	1 - BASIC CUSTODIAL CARE (CLOSED)	L - LOCAL	Native	yes	adjacent to creek creating braiding	2	yes	trail is in the water	3	yes	Sensitive species	2	Herbaceous sp. For shrews	7	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
20	4	7.0	Osha Canyon	1 - BASIC CUSTODIAL CARE (CLOSED)	1 - BASIC CUSTODIAL CARE (CLOSED)	L - LOCAL	Native	yes	adjacent to creek creating braiding	2	yes	trail is in the water	3	yes	Sensitive species	2	Herbaceous sp. For shrews		7	yes
22A	4	6.0	Agua Piedra-Comales	1 - BASIC CUSTODIAL CARE (CLOSED)	1 - BASIC CUSTODIAL CARE (CLOSED)	L - LOCAL	Native	yes	adjacent to creek creating braiding	2	yes	trail is in the water	3	yes	Sensitive species	2	Herbaceous sp. For shrews		7	yes
19A	4	6.1	Agua Piedra	1 - BASIC CUSTODIAL CARE (CLOSED)	1 - BASIC CUSTODIAL CARE (CLOSED)	L - LOCAL	Native	yes	adjacent to creek creating braiding	2	yes	trail is in the water	3	yes	Sensitive species	2	Herbaceous sp. For shrews		7	yes
19D	4	~1	Saddle to knob	1 - BASIC CUSTODIAL CARE (CLOSED)	1 - BASIC CUSTODIAL CARE (CLOSED)	L - LOCAL	Native	yes	adjacent to creek creating braiding	2	yes	trail is in the water	3	yes	Sensitive species	2	Herbaceous sp. For shrews		7	yes
103	6	0.1	Sublette	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	Collector	IMP - IMPROVED NATIVE MATERIAL	none noted	Road has good leadout drainages, provides good access throughout the year. Winter use is limited to Snowmobiles Road in fair condition	1	yes	wet meadows	2	None	FR 103 is used by the public during hunting seasons, Sept. through December.	1	Cumbres Railroad track crosses FR103 approximate 1/4 mile from 194 junction.	1	5	yes
103A	6	0.5	Sublette	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector	Native	none noted	Winter use is limited to Snowmobiles	1	none noted	none noted	1	None	FR 103 is used by the public during hunting seasons, Sept. through December.	1	dispersed camping access to allotments may access sublette station	1	4	no
103B	6	0.1	Sublette	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector	Native	none noted	Winter use is limited to Snowmobiles	1	none noted	none noted	1	None	FR 103 is used by the public during hunting seasons, Sept. through December.	1	dispersed camping access to allotments may access sublette station	1	4	no
111A	6	0.3	Off of FR 42	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion at drainage crossing	2	watershed conflicts	may be attributing to sediment to Rio Tusas	2	None	Big game habitat	1	road rarely used	1	6	no
111A2	6	0.6	Off of FR 42 to private	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion at drainage crossing	2	watershed conflicts	may be attributing to sediment to Rio Tusas	2	None	Big game habitat	1	access to private road with limited use	1	6	no
111C	6	0.6	Off of FR 42	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road goes up the drainage		washed conflicts	may be attributing to sediment to Rio Tusas	2	None	Big game habitat	1	christmas tree harvest road	1	4	no
111D	6	1.7	Abeyta Lake	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road washed out	3	none noted	none noted	1	None	big game habitat and turkey	1	dispersed camping, Abeyta Lake nearby wild horses from El Rito may access area, invasive weeds	1	6	no
111E	6	0.9	American Spring	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	some erosion occurring naturally	1	none noted	none noted	1	None	big game habitat and turkey	1	some ATV use invasive weeds	1	4	no

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES				
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
111F	6	0.8	Tusas Box	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted		1	none noted	none noted	1			1	None noted	1	4	no
118	6	0.0	San Antonio Mntn	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Once road gets wet, road becomes almost impassable to high clearance vehicles. Cobble soils Road is rutted and only gets worse during rainy weather	3	yes	Road maintains its saturation for quite some time after it get wet.	2	yes	Road lies north of San Antonio Mountain an area used as big game winter habitat	2	Sheep herders utilized this road as well to set up camp at the base of San Antonio Mountain. Access to private lands Tbone/BLM/hunting use high	1	8	yes
118A	6	0.4	San Antonio Mntn	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	steep slope/erosion?	2	none noted	none noted	1	yes	big game wintering habitat and migration corridors	2	un-authorize motorized travel to San Antonio Mt.	1	6	no
118B	6	0.8	San Antonio Mntn	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	steep slope/erosion?	2	none noted	none noted	1	yes	big game wintering habitat and migration corridors	2	un-authorize motorized travel to San Antonio Mt. Access to Game Dept. tank. Used by sheep grazing permittee for sheep camp	1	6	no
133	6	0.4	Cisneros Park/Stewart Meadows	3 - SUITABLE FOR PASSENGER CARS	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Slippery conditions exists for about 1/2 mile to the junction of FR80. Road through Cisneros part fairly good condition to FR 87 with rocky conditions at Lucero Lakes From junction of Highway 64 to about 3/4 to 1 mi. FR 133 gets real muddy when it rains, with slick mud	2	yes	FR 133 at Beehive Springs as it goes uphill very slippery when wet. Slippery when wet. This road receives road maintenance once a year.	2	yes	The area around Cisneros Park is a preferred habitat area by wintering wildlife	2	Permittees use this road to access allotments, set up camps along the road during allotment maintenance. Dispersed camping sites exists along the road. crosses private lands Smith properties at 64	1	7	yes
133D1	6	0.0	Beehive Springs	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	highly erodable soils May get slippery when wet	3	yes	may be attributing to sediment to the Rio Tusas	2	None	Big game habitat	2	very limited us, currently close, not known whether provides access to private	1	8	no
133D	6	0.5	Boothill Corral	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local		yes	May get slippery when wet	2	none noted	none noted	1	none	none	1	Road used primarily by Pvt land owners and BLM	1	5	no
133E	6	0.3	Lucero Lakes	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Loss of soil, thus exposing rocks making access difficult May get slippery when wet Rocky road from junction of 133 to the top of Lucero Lakes	2	yes	Soil tends to wash during heavy rainstorms Sediment delivery to FR 133 (Tusas Creek)	2	yes	Area more of a winter habitat than summer	2	Permittees and FS use this road to access Lucero Lakes and for maintenance of the top rail fence and water gaps.	1	7	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
133F	6	1.6	Broke Off Mountain	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Road gets real slippery when wet. Road is an old logging road periodically used by hunters. Some areas along the road act as a drainage	1	yes	Road objective level was to close road, considered a level II. Road runs right up the drainage. Road is a tight access to the upper reaches of Broke-Off Mt. There are no drainage fields, some erosion has occurred over time	2	None	big game habitat	1	Road is difficult even for a high clearance vehicle. Unauthorized motorized travel. Range management needs road due to distances	1	5	no
164TBB	6	0.2	Hondo #2	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	minimal soil conflicts	1	none noted	none noted	1	None	big game and turkey	1	hunting use, project implementation road	1	4	no
167	6	0.3	Cisneros Park/US 64	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	The area described in I, gets very muddy, causes sediment delivery to the bottom drainages. From junction of 167A and 576 road is rutted. Road collects moisture during rain storms	2	yes	Mud puddles are very evident, not much drainages associated with this road	2	None	elk enclosure in Martinez canyon area dispersed camping on user created road old timber sale area needs to be added to system	1	FR 167 accesses a portion of the district by recreationists and hunters	1	6	yes
167A	6	0.1	Barela Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Erosion within one mile of private land, within drainage. Limited pvt acces, Part of road on ridge, part of it on bottom	1	yes	Erosion occuring	2	none	none	1	Road goes through pvt, comes out through private with public lands in the middle	1	5	yes
167B1	6	0.6	Beehive Springs	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Soil loss due to erosion. A short road, with erosion taking place	2	yes	Same No drainage. Road is within the drainage	2	none	none	1	Access to private land. Need to find out who land owner is.	1	6	no
167G	6	1.8	Sawmill Creek/Horseshoe	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Soil loss due to erosion. First 1/2 mile, high gradient and very rocky	1	yes	Drainage to the Arroyo Aguade de la Petaca First 1/2 mile Road is very rocky and steep	2	yes	TES species may be present	3	Main access to Tusas Ridge from north going south.	1	7	yes
178D	6	1.3	Hopewell Ridge	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	soil loss due to erosion. 178D is boggy, goes through meadow	2	yes	Soil tends to wash during heavy rainstorms Soils fragile and vulverable	2	none	none	1	Dispersed camping, livestock herding,	1	6	no
1864	6	9.7	Sawmill Creek	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Road gets very muddy and collects much water at Dry Lakes. Receives heavy vehicular use	2	yes	Enclosed watershed, retains rainwater and snowmelt leading to increase erosion concern.	2	yes	TES species may be present	3	Access by permittees, fuelwood gatherers, heavy local use	1	8	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
1864A	6	3.9	Sawmill Creek	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	soils within road, stable First 1/4 mile rocky and muddy. Thereafter, road is in fair condition.	1	yes	Good drainage after the first 1/4 mile	1	yes	turkey hunting atv use closed roads access the area ongoing projects fuelwood, fire activitiess, dispersed camping	2	Access by permittees, fuelwood gatherers, heavy local use	1	5	yes
1864AB	6	0.7	Valdez Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted		1	none noted	none noted	1	yes	turkey hunting atv use closed roads access the area ongoing projects fuelwood, fire activitiess, dispersed campingbig game and turkey	2	fuelwood Dry Lakes II project implementation	1	5	no
1864TC	6	0.5	Sawmill Creek	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Road on ridge, no watershed concerns. Spur road follows alongside 1864. Road is very short in distance	1	none noted	none noted	1	yes	turkey hunting atv use closed roads access the area ongoing projects fuelwood, fire activitiess, dispersed camping	2	Access by permittees, fuelwood gatherers, heavy local use	1	5	no
1865	6	1.3	Sawmill Creek	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	Good drainage. Road is in fair condition	1	none noted	none noted	1	TES	TES species may be present turkey hunting atv use	3	Dry Lakes II project implementation Rx Burn, fuelwood gathering, until approx. 2009	1	6	yes
1873	6	2.3	Hopewell Ridge	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	At beginning of in meadow there is a big mud hole, Good drainage from there on rest of road Road in fair condition	1	none noted	Road has good drainage.	1	None	none	1	Road is holding together with good side vegetation to hold road intact. Heavily used by recreationists, hiking, hunters, fuelwood removal	1	4	yes
1893	6	4.4	Jawbone Mountain	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	some soil movement occurs, water holds on road	2	none noted	culvert maintenance needed	1	yes	seasonal wildlife closure	2	dispersed camping, range use, fuelwood gathering, hiking	1	6	yes
1893B1	6	0.8	Jawbone Mountain	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	Good drainage Road located on ridgetop.	1	yes	road drops down to private land	2		Timing restrictions Existing elk calving area	2	road access private land	1	6	no
222	6	0.1	Las Tablas/TP road	4 - MODERATE DEGREE OF USER COMFORT	3 - SUITABLE FOR PASSENGER CARS	Collector	IMP - IMPROVED NATIVE MATERIAL	yes	At Agua Canyon, road is drained by canyon Road graveled for the first 3 miles	1	yes	Road is under a county/ Forest Service maintenance agreement with heavy vehicular use. Most culverts are plugged. These need immediate attention. Road is eroding at a fast speed. Entire road needs periodic maintenance	2	none	none	1	Maintenance is a forest service/county responsibility under the agreement	1	5	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
284	6	0.0	Sublette	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	High vehicular use travel leads to sediment delivery into Rio Los Pinos. High flow also contributes to sediment delivery. Rio Los Pinos is on road bed.	2	none noted	Road requires periodic maintenance Vehicular use and high flow	1	yes	Fisheries concern based on sediment	2	High use recreation area with established campgrounds, restroom facilities, Road used by private landowners to access private land.	1	6	yes
285C	6	0.1	Servilleta area	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Clay soils with minimal soil movement Road located on flatland. Soils saturated when wet.	2	yes	saturated soils with erosion into the Arroyo Aguage de la Petaca.	2	yes	Area considered for timing restrictions wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking access private lands	1	7	yes
285D	6	0.1	Servilleta area	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Clay soils with minimal soil movement Road located on flatland. Soils saturated when wet.	2	yes	saturated soils with erosion into the Arroyo Aguage de la Petaca.	2	yes	Area considered for timing restrictions wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking	1	7	yes
285D1	6	0.0	Servilleta area	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Clay soils with minimal soil movement Road located on flatland. Soils saturated when wet.	2	yes	saturated soils with erosion into the Arroyo Aguage de la Petaca.	2	yes	Area considered for timing restrictions wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking access private lands	1	7	yes
285E	6	0.0	Servilleta area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Clay soils with minimal soil movement Road located on flatland. Soils saturated when wet.	2	yes	saturated soils with erosion into the Arroyo Aguage de la Petaca.	2	yes	Area considered for timing restrictions wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking access private lands	1	7	no
285F	6	0.0	Cerro Mojino Loop	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Clay soils with minimal soil movement Road located on flatland. Soils saturated when wet.	2	yes	saturated soils with erosion into the Arroyo Aguage de la Petaca.	2	yes	Area considered for timing restrictions wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking	1	7	yes
285F1	6	0.5	Cerro Mojino Loop	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Clay soils with minimal soil movement Road located on flatland. Soils saturated when wet.	2	yes	saturated soils with erosion into the Arroyo Aguage de la Petaca.	2	yes	Area considered for timing restrictions wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking access to Cerro Mojino Repeater	1	7	no
285F3	6	0.5	Cerro Mojino Loop	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Clay soils with minimal soil movement Road located on flatland. Soils saturated when wet.	2	yes	saturated soils with erosion into the Arroyo Aguage de la Petaca.	2	yes	Area considered for timing restrictions wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking	1	7	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
285G	6	0.1	Cerro Mojino Loop	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Clay soils with minimal soil movement Road located on flatland. Soils saturated when wet.	2	yes	saturated soils with erosion into the Arroyo Aguage de la Petaca.	2	yes	Area considered for timing restrictions	2	Livestock permiitees, fuelwood gathering, pinon picking	1	7	no
285G2	6	0.1	Taos Junction	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Clay soils with minimal soil movement Road located on flatland. Soils saturated when wet.	2	yes	saturated soils with erosion into the Arroyo Aguage de la Petaca.	2	yes	Area considered for timing restrictions	2	Livestock permiitees, fuelwood gathering, pinon picking access private lands	1	7	no
285G3	6	0.4	Taos Junction	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Clay soils with minimal soil movement Road located on flatland with rutty conditions from past vehicular activity. Soils saturated when wet	2	yes	saturated soils with erosion into the Arroyo Aguage de la Petaca.	2	yes	Area considered for timing restrictions	2	Livestock permiitees, fuelwood gathering, pinon picking access private lands	1	7	no
285G4	6	0.0	Taos Junction	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Clay soils with minimal soil movement Road located on flatland with rutty conditions from past vehicular activity. Soils saturated when wet	2	yes	saturated soils with erosion into the Arroyo Aguage de la Petaca.	2	yes	Area considered for timing restrictions	2	Livestock permiitees, fuelwood gathering, pinon picking. Private access issue	1	7	no
285I	6	1.2	Commanche	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soil eroding, where road closes arroyos road is in bad shape.	2	yes	Drainage to the Ojo Caliente	2	yes	big game habitat Area considered for timing restrictions	2	livestock permiitess, fuelwood gathering	1	7	no
285J	6	0.1	Commanche	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soil eroding, where road closes arroyos road is in bad shape.	2	yes	Drainage to the Ojo Caliente	2	yes	big game habitat Area considered for timing restrictions	2	livestock permiitess, fuelwood gathering private land access	1	7	yes
285J1	6	0.1	Commanche	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soil eroding, where road closes arroyos road is in bad shape.	2	yes	Drainage to the Ojo Caliente	2	yes	big game habitat Area considered for timing restrictions	2	livestock permiitess, fuelwood gathering private land access	1	7	yes
285K	6	0.1	Servilleta area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	gullyng roads when wet, slippery when wet	2	yes	Drainage of sediment to Aguaje	2	yes	Area considered for timing restrictions	2	fuelwood gathering	1	7	yes
285K2	6	0.1	Servilleta area	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	muddy when wet, clay soils, rut within the road system	2	yes	Drainage of sediment to Aguaje	2	yes	Area considered for timing restrictions	2	fuelwood gathering	1	7	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
285L	6	0.3	TCLP	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	285L (north) by the B-B ranch graveled for one mile. From that point on to the east the road become rutted. 285L (south) and south of B-B very erodable, gullies down the middle of road	2	yes	Drainage of sediments to arroyos and tanks, then into the Aguaje.	2	yes	Area considered for timing restrictions	2	fuelwood gathering, hunting access	1	7	yes
285N	6	1.6	TCLP	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road is rutted and muddy during wet.	2	yes	drainage of sediments to area stock tanks and arroyos to Aguaje	2	yes	Area considered for timing restrictions	2	fuelwood gathering, hunting access	1	7	yes
285P	6	0.3	Embudo Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	soils erosion, occuring due to road going down Canada Embudo, gullying occuring on road	2	yes	drainage of sediments into Canada Embudo	2	yes	no limitation in timing at this point	2	fuelwood gathering, hunting access	1	7	yes
285Q	6	0.2	Radio Towers	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	soil erosion, sandy soils in portions of road, othe portions muddy when wet	2	yes	drainage of sediment into mud holes and Cananda Embudo	2	None	no limitation in timing at this point big game habitat	1	fuelwood gathering, hunting access	1	6	no
285TP	6	1.0	Microwave Tower/Sandlin Arroyo	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local		yes	soil occuring on road, road in drainage	2	yes	drainage of sediment to stock tanks and arroyos. Road is wash out at arroyo, has been relocated by users to av	3	None	no limitation in timing at this point big game habitat	1	fuelwood gathering, hunting access	1	7	yes
356A	6	0.8	Hopewell Lake	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Road located on rocky terrain leading down to old Hopewell Mining activity sites. road goes through Group Shelter at the Hopewell Campground	2	yes	Road crosses Placer Creek at the upper and lower end and at the confluence of Vallecitos Road system contributes to sediment delivery into the Placer Creek.	3	yes	fisheries and vehicular activity Fisheries concern based on sediment	2	Placer mining activity, mine shaft safety concern. Private land access and high ATV use	1	8	no
419	6	0.2	Broke Off Mountain	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Road causing erosion concerns Road rocky, accessible by high clearance and ATV's.	3	yes	3 miles into FR 419 when it starts climbing up Broke-off, road narrow, rocky, not suitable for trucks turning. Vehicles need to go to the top to be able to turn around. 1/4 mile from from 133, 419 collects water with no lead outs	2	none	none	1	Permittees, fuelwood gathering from Colorado residents.	1	7	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
419H	6	1.9	Broke Off Mountain	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local		yes	Road is located on a north slope with potential erosion issues. Road crosses two drainages	2	yes	Road continues to a dead end with potential sediment delivery to the Rio San Antonio Watershed.	2	yes	fisheries and vehicular activity Fisheries concern based on sediment	2	Permittees, fuelwood gathering from Colorado residents.	1	7	no
419H1	6	1.9	Broke Off Mountain	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local		yes	Road is located on a north slope with potential erosion issues.	2	yes	Road continues to a dead end with potential sediment delivery to the Rio San Antonio Watershed.	2	yes	fisheries and vehicular activity Fisheries concern based on sediment	2	Permittees, fuelwood gathering from Colorado residents.	1	7	no
419H2	6	0.5	Broke Off Mountain	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local		yes	Road is located on a north slope with potential erosion issues.	2	yes	Road continues to a dead end with potential sediment delivery to the Rio San Antonio Watershed.	2	yes	fisheries and vehicular activity	1	Permittees, fuelwood gathering from Colorado residents.	1	6	no
42	6	10.7	Tusas/Vallecitos	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	Collector	Native	yes	For the first 3 miles, road slippery when wet, ruts, heavy traffic seasonally. Once it crosses the Tusas Box, road gets very bad when wet with ruts written on the landscape. main road between El Rito and Tres Piedras RD's	3	yes	Road contributes to sediment delivery to Rio Tusas. Erosion concerns from high vehicular activity	2	yes	fisheries and vehicular activity Fisheries concern based on sediment	2	Road accesses wild horse territory on the El Rito RD, used by public, hunting, hiking, animal viewing	1	8	yes
421	6	4.4	Biscara canyon	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	Collector	IMP - IMPROVED NATIVE MATERIAL	yes	Erosion control sediment traps placed strategically on some culverts that cross road. Traps reduce sediment delivery to Biscara Canyon and Rio Tusas. Graveled Road from US Highway 64 to about 4 miles.	1		Road is on our annual maintenance schedule. Road could use increase maintenance. Road was the main trailing corridor for grant and permitted livestock. Riparian trainings scheduled within the riparian bottom. Road is one of the major use roads on the district, accessing the northern portion of the district.	1	none	none	1	transition zone for wildlife, main access north and south on district	1	4	yes
421C	6	3.1	Biscara Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	soil loss due to erosion.	2	none noted	none noted	1	none	none	1	fuelwood gathering and livestock permittees use, hunting access and dispersed camping	1	5	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
494	6	0.0	Sublette	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector	Native	yes	soil erosion due to road following drainage bottom. Portion of this road not contributing to soil erosion on ridge. At souther end of road steep incline contributing to sediment delivery to Rio De los Pinos	2	yes	sediment delivery to Rio de los Pinos	3	yes	fisheries concerns based on sediment to Rio de los Pinos	3	Access to railroad and access to private land	1	9	yes
551	6	0.1	TCLP	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector	Native	yes	In some areas of 551, road is eroding away...losing road surface.Road locatd on flatland. Soils saturated when wet. Erosion occurring in T26N R10E Sect. 22 and T26N R10E Sect. 10. These areas contributing to the degradation to road. Erosion at Section 15 Tank	2	yes	Road is one of the major use roads on the district, accessing the northern portion of the district.	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, archy site located T26N R10E Sect.22. Section 15 tank; Major wood hauling for pinon wood cultural resource concerns.	1	7	yes
5512B	6	0.2	TCLP	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551A	6	0.1	TCLP	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551B	6	0.4	TCLP	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551E	6	0.7	TCLP	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551F	6	0.1	TCLP	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551F1	6	0.8	TCLP	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551G	6	0.0	TCLP	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system	
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts			Criteria
551H	6	0.1	TCLP	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551I	6	0.5	TCLP	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551I2	6	0.3	TCLP	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551I3	6	0.8	TCLP	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551I4	6	1.7	TCLP	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood. Main access to subdivision and grazing	1	7	yes
551J	6	0.0	TCLP	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551K	6	0.5	TCLP	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551L	6	0.1	TCLP	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551M	6	1.0	TCLP	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551N	6	0.3	TCLP	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	yes
551P	6	0.1	TCLP	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES				
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
551Q	6	0.0	TCLP	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	yes
551Q1	6	0.1	TCLP	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551R	6	0.2	TCLP	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
551S	6	0.0	TCLP	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Aguaje	2	yes	suggested timing restrictions for big game habitat wildlife winter habitat disturbance	2	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	7	no
556	6	0.0	Powerline road/to Ojo Caliente	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Arroyos and stock tanks	2	none	no suggested timing restrictions big game habitat	1	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	6	yes
556A	6	0.3	North powerline/private	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Arroyos and stock tanks	2	none	no suggested timing restrictions big game habitat	1	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	6	no
556B	6	0.2	Powerline/Pilar area	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Arroyos and stock tanks	2	none	no suggested timing restrictions big game habitat	1	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	6	no
556B2	6	0.2	Pilar area	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Arroyos and stock tanks	2	none	no suggested timing restrictions big game habitat	1	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	6	no
556B3	6	0.2	Pilar area	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Arroyos and stock tanks	2	none	no suggested timing restrictions big game habitat	1	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	6	no
556C	6	1.0	Pilar area	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Arroyos and stock tanks	2	none	no suggested timing restrictions big game habitat	1	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	6	no
556D	6	0.7	Powerline/Boundary	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Arroyos and stock tanks	2	none	no suggested timing restrictions big game habitat	1	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	6	no

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
556F	6	1.4	Cerro Azul	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Arroyos and stock tanks	2	none	no suggested timing restrictions big game habitat	1	Livestock permittees, fuelwood gathering, pinon picking, Major wood hauling for pinon wood	1	6	no
556H	6	0.7	558 to Ojo Caliente	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Arroyos and stock tanks	2	none	no suggested timing restrictions big game habitat	1	no suggested timing restrictions	1	6	no
557	6	0.2	Chile Line/ Taos Junction	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector	Native	yes	On some areas of road soil is eroding into arroyos.	2	yes	May be contributing to depositing soil into the Arroyos and stock tanks	2	none	no suggested timing restrictions big game habitat	1	no suggested timing restrictions	1	6	yes
557B	6	0.4	Noria Arroyo/hartig Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soils erodable	2	none noted	none noted	1	none	no suggested timing restrictions big game habitat	1	fuelwood gathering, hunting,	1	5	no
557B1	6	0.1	Embudo/Chile Line	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soils erodable	2	none noted	none noted	1	none	no suggested timing restrictions big game habitat	1	fuelwood gathering, hunting,	1	5	no
557B2	6	0.2	Hartig tank	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soils erodable	2	none noted	none noted	1	none	no suggested timing restrictions big game habitat	1	fuelwood gathering, hunting,	1	5	no
557C	6	0.3	Noria/Barranca	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soils erodable	2	none noted	none noted	1	none	no suggested timing restrictions big game habitat	1	fuelwood gathering, hunting,	1	5	no
557D	6	0.5	Powerline/Barranca	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soils erodable	2	none noted	none noted	1	none	no suggested timing restrictions big game habitat	1	fuelwood gathering, hunting,	1	5	no
557E	6	0.0	Barranca	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soils erodable	2	none noted	none noted	1	none	no suggested timing restrictions big game habitat	1	fuelwood gathering, hunting,	1	5	no
557F	6	0.0	Barranca	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soils erodable	2	none noted	none noted	1	none	no suggested timing restrictions big game habitat	1	fuelwood gathering, hunting,	1	5	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
557G	6	0.0	Barranca/boundary	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soils erodable	2	none noted	none noted	1	none	no suggested timing restrictions big game habitat	1	fuelwood gathering, hunting,	1	5	no
557H	6	0.8	Embudo/Barranca	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soils erodable	2	none noted	none noted	1	none	no suggested timing restrictions big game habitat	1	fuelwood gathering, hunting,	1	5	no
557J	6	0.7		2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soils erodable	2	none noted	none noted	1	none	no suggested timing restrictions big game habitat	1	fuelwood gathering, hunting,	1	5	no
558	6	0.7	Ojo Caliente/Comanche	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector	Native	yes	sandy soils erodable	2	none noted	none noted	1	none	no suggested timing restrictions big game habitat	1	fuelwood gathering, hunting,	1	5	no
558A	6	0.0	Stevens/Sandlin Arroyo	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soils erodable	2	none noted	none noted	1	none	no suggested timing restrictions big game habitat	1	fuelwood gathering, hunting,	1	5	no
558B	6	0.5	Sandlin Arroyo/Powerline	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soils erodable	2	none noted	none noted	1	none	no suggested timing restrictions big game habitat	1	fuelwood gathering, hunting,	1	5	no
558TAL	6	1.7	Vibora tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	soil occuring on road, road in drainage	2	none noted	none noted	1	none	no suggested timing restrictions big game habitat	1	fuelwood gathering, hunting,	1	5	no
558TR	6	2.1	Microwave tower/private land	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	soil occuring on road, road in drainage	2	yes	drainage of sediment to stock tanks and arroyos. Road is wash out at arroyo, has been relocated by users to av	2	none	no suggested timing restrictions big game habitat	1	fuelwood gathering, hunting access	1	6	no
572	6	0.5	Cruces Basin Wilderness	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Soil erosion at the junction of FR 87 and FR 572 for approx. 1 mile. Rocky from that point to the dead end trail head	1	none noted	none noted	1	none	none	1	dispersed camping at trailhead, road goes through the Cruces Basin Wilderness. Permittees (Apache) may want a horse camp at end of road for 45 days.	1	4	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
576	6	7.7	Mule Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector		yes	Soil erosion at T29N R8E Sect. 25 and 26 and along drainage bottoms and contributing sediment to stock tanks.	2	yes	watershed issues such as sedimentation are localized in nature from current and increase vehicular use. Ruts are deep. Road need high maintainane to adequatly to make travel safe.	2	yes	big game wintering habitat	2	livestock grazing, fuelwood gathering, dispersed camping associated with hunting. Road needs archy clearance	1	7	yes
578	6	9.2	Tio Gordito/Amado r/L Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	soil conflict exists where road has not been maintained at the lower end of 578. Soil conflicts improved where maintenance has occurred associated with the Red Mesa Project at the northern half of road.	2	yes	watershed conditions have improved since maintenance has occurred in conjunction with the Red Mesa Veg Management Project.watershed has been improved	2	yes	TES may be present in area	3	FR 578 has been maintained for forest vegetation management activities. Currently the public may use this road but public may not remove fuelwood until implementation has been completed.	1	8	yes
578A	6	2.6	Tio Gordito/Amado r/L Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	soil erosion occurs when road gets wet and sediment is move. At FR 578 and 578A is rutted and potential to create more soil conflicts especially where wate is channeling in the middle of the road.	2	yes	sediment delivery to stock tanks.	2	yes	big game wintering habitat	2	FR 578A accesses private land from US 285. Heavy traffic from local community.	1	7	yes
578B	6	1.4	Tio Gordito/Amado r/L Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	soil erosion occuring in areas of road, rocky on portions, rutted and potential to create more soil conflicts especially where wate is channeling in the middle of the road.	2	none noted	none noted	1	yes	TES may be present in area	3	fuelwood gathering, hunting access	1	7	no
578C	6	1.3	Tio Gordito/Amado r/L Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	soil erosion occuring in areas of road, rocky on portions, rutted and potential to create more soil conflicts especially where wate is channeling in the middle of the road.	2	none noted	none noted	1	yes	TES may be present in area	3	fuelwood gathering, hunting access	1	7	no
578D	6	1.0	Tio Gordito/Amado r/L Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	soil erosion occuring in areas of road, rocky on portions, rutted and potential to create more soil conflicts especially where wate is channeling in the middle of the road.	2	none noted	none noted	1	yes	TES may be present in area	3	fuelwood gathering, hunting access	1	7	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
578D1	6	1.0	Tio Gordito/Amador/L Tank	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	soil erosion occurring in areas of road, rocky on portions, rutted and potential to create more soil conflicts especially where wate is channeling in the middle of the road.	2	none noted	none noted	1	yes	TES may be present in area	3	fuelwood gathering, hunting access	1	7	no
578D2	6	0.9	Tio Gordito/Amador/L Tank	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	soil erosion occurring in areas of road, rocky on portions, rutted and potential to create more soil conflicts especially where wate is channeling in the middle of the road.	2	none noted	none noted	1	yes	TES may be present in area	3	fuelwood gathering, hunting access	1	7	no
578D3	6	0.1	Tio Gordito/Amador/L Tank	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	soil erosion occurring in areas of road, rocky on portions, rutted and potential to create more soil conflicts especially where wate is channeling in the middle of the road.	2	none noted	none noted	1	yes	TES may be present in area	3	fuelwood gathering, hunting access	1	7	no
578D4	6	1.2	Tio Gordito/Amador/L Tank	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	soil erosion occurring in areas of road, rocky on portions, rutted and potential to create more soil conflicts especially where wate is channeling in the middle of the road.	2	none noted	none noted	1	yes	TES may be present in area	3	fuelwood gathering, hunting access	1	7	no
578G	6	1.0	Tio Gordito/Amador/L Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	soil erosion occurring in areas of road, rocky on portions, rutted and potential to create more soil conflicts especially where wate is channeling in the middle of the road.	2	none noted	none noted	1	yes	TES may be present in area	3	fuelwood gathering, hunting access	1	7	no
578R1	6	0.5	Tio Gordito/Amador/L Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	soil erosion occurring in areas of road, rocky on portions, rutted and potential to create more soil conflicts especially where wate is channeling in the middle of the road.	2	none noted	none noted	1	yes	TES may be present in area	3	fuelwood gathering, hunting access	1	7	no
578R2	6	0.3	Tio Gordito/Amador/L Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	soil erosion occurring in areas of road, rocky on portions, rutted and potential to create more soil conflicts especially where wate is channeling in the middle of the road.	2	none noted	none noted	1	yes	TES may be present in area	3	fuelwood gathering, hunting access	1	7	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
578R3	6	0.1	Tio Gordito/Amador/L Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	soil erosion occurring in areas of road, rocky on portions, rutted and potential to create more soil conflicts especially where water is channeling in the middle of the road.	2	none noted	none noted	1	yes	TES may be present in area	3	fuelwood gathering, hunting access	1	7	no
578R5	6	0.3	Tio Gordito/Amador/L Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	soil erosion occurring in areas of road, rocky on portions, rutted and potential to create more soil conflicts especially where water is channeling in the middle of the road.	2	none noted	none noted	1	yes	TES may be present in area	3	fuelwood gathering, hunting access	1	7	no
579	6	4.3	Petaca Peak	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Erosion occurring, road not recommended for public access due to its deteriorating conditions. Road is eroding at a high rate, exposing large boulders.	3	yes	Road is closed off at FR 97 and at Highway 222 seasonally for big game disturbances. Erosion occurring, road not recommended for public access due to its deteriorating conditions. Road is eroding at a high rate, exposing large boulders.	3	none	none	1	road not suitable for public travel	1	8	no
600	6	0.5	Tres Orejas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Road on flatland with stable soils. Road goes through sagebrush crested wheatgrass, with some rutting and erosion occurring at the allotment boundary.	2	yes	Road Sediment delivery into Stover Stock Tank	2	none	none	1	fuelwood gathering, permittees, private land access issues. Permittee request maintenance for hauling water to a metal drinker	1	6	yes
600A	6	0.0	Tres Orejas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Road on flatland with stable soils. Road goes through sagebrush crested wheatgrass, with some rutting and erosion occurring	2	yes	Road Sediment delivery occurring locally	2	none	none	1	fuelwood gathering, permittees, private land access issues.	1	6	yes
601	6	0.5	Tres Orejas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Road on flatland with stable soils. Road is approximately 1 mile long ending at a private gate	1	yes	Road Sediment delivery occurring locally	2	none	none	1	fuelwood gathering and livestock permittees use	1	5	no
602	6	0.4	Tres Orejas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	same soil conflicts with some localized rutting and erosion occurring	1	yes	Deep ruts on the North side of road contributing to soil loss.	2	none	none	1	fuelwood gathering and livestock permittees use	1	5	yes
602A	6	0.2	Tres Orejas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	same soil conflicts with some localized rutting and erosion occurring	1	yes	Deep ruts on the North side of road contributing to soil loss.	2	none	none	1	fuelwood gathering and livestock permittees use	1	5	no

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES				
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
602B	6	0.4	Tres Orejas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	same soil conflicts with some localized rutting and erosion occurring	1	yes	Deep ruts on the North side of road contributing to soil loss.	2	none	none	1	fuelwood gathering and livestock permittees use	1	5	no
603	6	0.4	Tres Orejas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	same soil conflicts with some localized rutting and erosion occurring	1	yes	Deep ruts on the North side of road contributing to soil loss.	2	none	none	1	fuelwood gathering and livestock permittees use	1	5	yes
604	6	1.7	Tres Orejas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	water does run off the road...no drainage. Water stay on road. Minimal soil movements	2	none noted	none noted	1	none	none	1	fuelwood gathering and livestock permittees use	1	5	yes
605	6	0.3	Tres Orejas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	water does run off the road...no drainage. Water stay on road. Minimal soil movements	2	none noted	none noted	1	none	none	1	fuelwood gathering and livestock permittees use. Private land access	1	5	yes
605A	6	0.0	Tres Orejas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	water does run off the road...no drainage. Water stay on road. Minimal soil movements	2	none noted	none noted	1	none	none	1	fuelwood gathering and livestock permittees use	1	5	no
605B	6	1.9	Tres Orejas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	water does run off the road...no drainage. Water stay on road. Minimal soil movements	1	none noted	none noted	1	none	none	1	fuelwood gathering and livestock permittees use. Private land access	1	4	no
645	6	1.4	Biscara	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	none noted	1	none noted	none noted	1	none	none	1	fuelwood gathering and livestock permittees use	1	4	no
64A	6	0.7	Gavilan	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	none,well vegetated...narrow barely visible in landscape	1	none noted	none noted	1	none	none	1	possible use by livestock permittees, access to grant	1	4	no
64B	6	1.1	Nutritas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road goes through several wet areas and is boggy in areas	3	yes	road attributes to sediment delivery to mostly the Rio Brazos Watershed.	2	yes	no limitations in seasonal use at this time big game spring/summer habitat	1	used by livestock permittees. Unauthorized motorized travel. Gated and trenched at US 64	1	7	no
64B	6	0.0	Gavilan	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road goes through several wet areas and is boggy in areas	3	yes	road attributes to sediment delivery to mostly the Rio Brazos Watershed.	2	yes	no limitations in seasonal use at this time big game habitat	1	used by livestock permittees. Unauthorized motorized travel. Gated and trenched at US 64	1	7	no
64D	6	0.0	Gavilan	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road attributes to soil conflicts as road is not gravel. Ruts present on road	2	yes	road attributes to sediment delivery to mostly the Rio Brazos Watershed.	2	none	no limitations in seasonal use at this time big game summer habitat	1	possible use by livestock permittees, access to grant	1	6	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
64D1	6	0.2	Gavilan	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road attributes to soil conflicts as road is not graveled. Ruts present on road	2	yes	road attributes to sediment delivery to mostly the Rio Brazos Watershed.	2	none	no limitations in seasonal use at this time big game summer habitat	1	possible use by livestock permittees, access to grant	1	6	no
64D2	6	0.2	Hopewell Lake	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road attributes to soil conflicts as road is not graveled. Ruts present on road	2	yes	road attributes to sediment delivery to mostly the Rio Vallecitos Watershed.	2	none	no limitations in seasonal use at this time big game summer habitat	1	used by livestock permittees to access corral. Access to private. Used by ATVs near Hopewell Lake	1	6	no
64D3	6	1.0	Hopewell Lake	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road attributes to soil conflicts as road is not graveled. Ruts present on road	2	yes	road attributes to sediment delivery to mostly the Rio Vallecitos Watershed.	2	none	no limitations in seasonal use at this time big game summer habitat	1	used by livestock permittees to access corral. Access to private. Used by ATVs near Hopewell Lake	1	6	no
64G	6	0.5	Tres Piedras	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road in decent shape to Tom Bryan tank. Rutted in some spots. Soil conflicts from where road is closed at tank. Closed with water bars. Unrestricted motorized travel from that point	2	none noted	none noted	1	none	none	1	popular camp site for hunters and recreationist. Used by livestock permittees	1	5	no
64H	6	0.5	Tres Piedras	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road in bad shaped, rutted and not much gravel. Slick when wet. Lots of soil movement	3	yes	sediment delivery to Gurule tank	2	none	no limitations in seasonal use at this time big game wintering habitat	2	admin. Used to access well. Access to private property.	1	8	no
64J	6	0.5	Tres Piedras	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	water does run off the road...no drainage. Water stay on road. Minimal soil movements	3	yes	sediment delivery to arroyos and tanks	1	none	none	1	access to private land. Access to rock climbing and camping site.	1	6	no
64TH	6	2.0	Sawmill	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road is water barred, soil movement into arroyo adjacent to road	2	yes	sediment delivery via arroyos to Rio Tusas	2	none	none	1	used by livestock permittees and hunters	1	6	no
663	6	0.5	Nutritas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road not open to motorized travel. Ruts occur on road when wet. Soil movement to drainages and arroyos	1	none noted	none noted	1	none	none	1	used by livestock permittees and hunting camps	1	4	no
675B	6	0.7	Sawmill Creek	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	none	1	none noted	none noted	1	none	none	1	fuelwood gathering, livestock permittees and hunters use	1	4	no
675TAA	6	0.9	Sawmill Creek	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Erosion occurring on portions of road	1	yes	minimal sediment delivery minor watershed conflicts	1	none	none	1	fuelwood gathering, livestock permittees and hunters use	1	4	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
686	6	0.1	Apache Creek	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector	Native	yes	erosion on road. No culverts	2	yes	sediment delivery to Arkansas Creek tributary and Rio del Los Pinos	2	none	no limitations in seasonal use at this time big game summer habitat	1	continental divide trail access, livestock permittees, campers, and hunter use	1	6	yes
686A	6	0.8	Apache Creek	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road. No culverts	2	yes	sediment delivery to Rio Brazos	2	none	no limitations in seasonal use at this time big game summer habitat	1	continental divide trail access, livestock permittees, campers, and hunter use	1	6	no
686A1	6	0.6	Apache Creek	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road. No culverts	2	yes	sediment delivery to Rio Brazos	2	none	no limitations in seasonal use at this time big game summer habitat	1	continental divide trail access, livestock permittees, campers, and hunter use	1	6	no
686A2	6	0.5	Apache Creek	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road. No culverts	2	yes	sediment delivery to Rio Brazos	2	none	no limitations in seasonal use at this time big game summer habitat	1	continental divide trail access, livestock permittees, campers, and hunter use	1	6	yes
686B	6	0.2	Apache Creek	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road. No culverts	2	yes	sediment delivery to Dixie Creek tributary and Rio del Los Pinos	2	none	no limitations in seasonal use at this time big game summer habitat	1	continental divide trail access, livestock permittees, campers, and hunter use	1	6	yes
712	6	3.7	Cunningham	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	Collector	IMP - IMPROVED NATIVE MATERIAL	none noted	none	1	none noted	none noted	1	none	big game habitat	2	fuelwood gathering, livestock permittees and hunters use, private land access	1	5	yes
712A	6	3.2	Cunningham	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	at beginning of road, road goes through Cunningham drainage	3	yes	sediment delivered to Rio Tusas	2	none	big game habitat	2	fuelwood gathering, livestock permissess and hunters use. Archy. Site in first half mile of road.	1	8	no
712B	6	2.0	Cunningham	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	at beginning of road, road goes through Cunningham drainage	3	yes	sediment delivered to Rio Tusas	2	none	big game habitat	2	fuelwood gathering, livestock permissess and hunters use.	1	8	no
712C	6	1.8	Cunningham Gulch	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road goes along Cunningham gulch	3	yes	road attributes to sediment delivery to Cunningham gulch stock tanks and Rio Tusas	2	none	big game habitat	2	fuelwood gathering, livestock permissess and hunters use. Archy. Sites on road. Access private land	1	8	no
712D	6	0.3	Cunningham	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road on high gradient, rutted in areas. Soil movement to drainage	2	yes	road attributes to sediment delivery to Cunningham gulch stock tanks and Rio Tusas	2	none	big game habitat	2	fuelwood gathering, livestock permissess and hunters use. Access private land	1	7	no
712D1	6	0.1	Butterfly Springs	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road on high gradient, rutted in areas. Soil movement to drainage	2	yes	road attributes to sediment delivery to Cunningham gulch stock tanks and Rio Tusas	2	none	big game habitat	2	fuelwood gathering, livestock permissess	1	7	no
712E	6	1.3	Cunningham	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Soil movement to drainage and stock tanks	2	yes	road attributes to sediment delivery to Willow creek and stock tank	2	none	big game habitat	2	fuelwood gathering, livestock permissess and hunters use.	1	7	no

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES				
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
712G	6	2.0	Cunningham	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	none, well vegetated, narrow barely visible on landscape	1	yes	may be contributing to depositing soil into Willow gulch	2	none	big game habitat	2	very limited use, due to water bars	1	6	no
718	6	3.8	Maquinita Canyon	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	some soil movement on unstable road surface at beginning of road near US 64. The rest of road in decent shape	1	yes	may be delivering sediment to Rio Tusas	2	none	big game habitat	2	fuelwood gathering, vegetation management project access, snowmobile and X county ski trail, hunting, closed at US 64 with gate, private land access.	1	6	no
718B	6	0.9	Maquinita Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Soil movement attributed to drainage crossing at Maquinita drainage	2	yes	may be delivering sediment to Rio Tusas	2	none	big game habitat	2	fuelwood gathering, vegetation management project access, snowmobile and X county ski trail, hunting, closed at US 64 with gate, private land access.	1	7	no
728	6	1.8	Maquinita Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	none, road on the ridge	1	none noted	none noted	1	none	big game habitat	2	fuelwood gathering, vegetation management project access, snowmobile and X county ski trail, hunting, closed at US 64 with gate, private land access. Beaver ponds	1	5	no
74	6	1.5	Osier	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road. Culverts filled up, gully, bad drainage, river crossings, deep pot holes on road Road in bad shape	3	yes	contributing to sediment deposit to Rio de los Brazos and Rio de los Pinos	2	none	no limitations in seasonal use at this time big game summer habitat	2	livestock permit use, dispersed camping, Access to Osier train station. Goes to Colorado border and connects to Colorado	1	8	yes
75	6	2.9	sublette	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local		yes	erosion on, does not drain well. Culverts clogged up	3	yes	contributing to sediment deposit to Rio de los Pinos	2	none	none	1	fuelwood gathering for Colorado res. Railroad uses for to access train track for maintenance. livestock permissess and hunters use.	1	7	yes
75A	6	0.0	Sublette	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road	2	yes	contributing to sediment deposit to Rio de los Pinos	2	none	none	1	access to BLM. Livestock permit use, hunting use.	1	6	no
75A1	6	1.0	Sublete	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road	2	yes	contributing to sediment deposit to Rio de los Pinos	2	none	none	1	access to BLM. Livestock permit use, hunting use.	1	6	no
75A2	6	0.8	Sublete	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road	2	yes	contributing to sediment deposit to Rio de los Pinos	2	none	none	1	access to BLM. Livestock permit use, hunting use.	1	6	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
78	6	0.2	Laguna Larga/Chino Lake	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots	2	yes	Gully erosion at beginning of road near junction of FR 87 contributing to sediment delivery to Rio San Antonio.	2	none	none	1	livestock permittee use, dispersed camping, hunting, fishing at Laguna Larga	1	6	yes
78A	6	0.0	Laguna Larga/Chino Lake	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots	2	yes	Gully erosion near road contributing to sediment delivery to Laguna Larga	2	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting, fishing at Laguna Larga	1	7	no
78A1	6	0.3	Laguna Larga/Chino Lake	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	Gully erosion near contributing to sediment delivery to Rio de los Pinos	2	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting, fishing at Laguna Larga	1	7	no
78A2	6	0.2	Laguna Larga/Chino Lake	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	Gully erosion near contributing to sediment delivery to Rio de los Pinos	2	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting,	1	7	no
78A3	6	0.5	Laguna Larga/Chino Lake	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	Gully erosion near contributing to sediment delivery to Rio de los Pinos	2	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting,	1	7	no
78A4	6	0.2	Laguna Larga/Chino Lake	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	Gully erosion near contributing to sediment delivery to Rio de los Pinos	2	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting,	1	7	no
78C	6	0.2	Laguna Larga	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	Gully erosion near contributing to sediment delivery to Rio de los Pinos	2	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting,	1	7	no
78D	6	0.2	Laguna Larga	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	Gully erosion near contributing to sediment delivery to Rio de los Pinos	2	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting,	1	7	no
795	6	5.0	Jawbone Mountain	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels down road and rutted where road goes through meadows at heads of drainages	2	yes	sediment delivery to drainages and stock tanks and Rio Tusas	2	yes	limitation of season of use 5/1 - 7/25 elk calving area	2	livestock permittee use, dispersed camping, hunting, access to private land	1	7	yes
795BB	6	1.2	Jawbone Mountain	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	non-use road	1	none noted	none noted	1	yes	limitation of season of use 5/1 - 7/25 elk calving area	2	road not used by motor vehicles. Foot travel only	1	5	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
795Y	6	0.7	Jawbone Mountain	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	non-use road	1	none noted	none noted	1	yes	limitation of season of use 5/1 - 7/25 elk calving area	2	road not used by motor vehicles. Foot travel only. R3quest for private access	1	5	no
80	6	12.3	Valle Grande	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Erosion on road where it goes through meadows such as Valle Grande and Posito. No drainage and becomes rutted.	3	yes	sediment delivery to drainages and stock tanks and Little Tusas river	2	none	no limitations in seasonal use at this time big game summer habitat	2	livestock permittee use, dispersed camping, hunting, access to private land	1	8	yes
80C	6	1.1	Valle Grande	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	non-use road	1	none noted	none noted	1	none	no limitations in seasonal use at this time big game summer habitat	2	livestock permittee use for camping, foot travel	1	5	no
80D	6	0.7	Valle Grande	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	non-use road	1	none noted	none noted	1	none	no limitations in seasonal use at this time big game summer habitat	2	livestock permittee use for camping, foot travel	1	5	no
80G	6	1.0	Beehive Springs	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion occurring on portions of road	2	yes	some sediment to drainages such as Little Tusas Creek on Private	2	none	no limitations in seasonal use at this time big game summer habitat	2	livestock permittee use and private land access.	1	7	no
80G2	6	0.7	Beehive Springs	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion occurring on portions of road	2	yes	some sediment to drainages such as Little Tusas Creek on Private	2	none	no limitations in seasonal use at this time big game summer habitat	2	livestock permittee use and private land access.	1	7	no
80J	6	1.6	Jawbone/Valle Grande	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	some erosion occurring on part road along Rio Tusas	2	yes	sediment delivery to Rio Tusas Creek on private	3	yes	Rio Grande Cutthroat Trout in Rio Tusas Fisheries concern based on sediment TES	3	main access to private property on this section of Rio Tusas	1	9	no
82	6	1.0	Mule Canyon/Barela Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion occurring on portions of road	2	yes	sediment delivery to Arroyo de las Aguaje attributed to road	2	none	no limitations in seasonal use at this time big game transition area	2	livestock permittee, access to and from private. Hunting	1	7	yes
82A	6	0.5	Upper Biscara	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion occurring on portions of road	2	yes	sediment delivery to arroyo or drainage road	2	none	no limitations in seasonal use at this time big game transition area	2	livestock permittee, hunting access	1	7	no
82B	6	0.6	Lamy Canyon	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	none noted	1	none noted	none noted	1	none	no limitations in seasonal use at this time big game transition area	2	livestock permittee, hunting access, limited foot travel	1	5	no
83	6	1.8	Loco Ridge	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion occurring on numerous portions of road below Loco Ridge and the head of Esqueibel Canyon.	2	yes	sediment delivery to Arroyo de las Aguaje attributed to road	2	none	no limitations in seasonal use at this time big game transition area	2	livestock permittee access, hunting access, dispersed camping, access to transfer site at lower end, Arterial road on district	1	7	yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
87	6	0.1	Lagunitas/US285	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	Collector	Gravel	yes	on the lower part of FR87 road in decent condition, washboarded. At upper portion of FR87 past junction of 87A near Lagunitas	2	yes	sediment delivery to Rio San Antonio, Rio Brazos, Conejos and Cruces Basin drainages.	2	none	no limitations in seasonal use at this time variety of wildlife habitat	2	one of the main artery roads on the district. Access for livestock permittees, desperered camping, hunting. CDT on FR 87 adjacent to	1	7	yes
871	6	0.5	Banco Julian	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion occuring on portions of road	2	none noted	none noted	1	none	no limitations in seasonal use at this time big game transition area	2	livestock permitte use, dispersed camping, hunting	1	6	no
871A	6	0.8	Nutritas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	none noted	1	none noted	none noted	1	none	no limitations in seasonal use at this time big game transition area	2	livestock permittee, hunting access, closed with berms, limited foot travel	1	5	no
87A	6	0.0	Fire Steel Road	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	Collector	Native	none noted	none noted	1	none noted	none noted	1	none	no limitations in seasonal use at this time big game summer habitat	2	livestock permitte use, dispersed camping, hunting	1	5	yes
87A	6	0.1	Fire Steel Road	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	Collector	Native	none noted	none noted	1	none noted	none noted	1			1	livestock permitte use, dispersed camping, hunting	1	4	yes
87AA	6	0.8	Fire Steel Road	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion occuring on severnal portions of the road	1	yes	high Sediment delivery to Tio Grande and Rio San Antonio road adjacent to drainage	3	yes	Fisheries conflict with sediment to drainages high elk use in spring TES fish	3	access to private land, livestock permittee use, hunting and fishing use	1	8	yes
87AD	6	4.5	Tio Grande	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector	Native	yes	erosion occuring on severnal portions of the road	1	yes	none noted	1	yes	big game summer habitat	2	livestock permitte use, dispersed camping, hunting	1	5	yes
87B	6	0.4	Lagunitas Campground	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion occuring on severnal portions of the road going to lower campground	2	yes	sediment attributed to beaver ponds and Rio San Antonio	2	yes	Fisheries conflict with sediment to Lagunita Lakes Fisheries and Big game summer habitat	2	access to lower campground	1	7	yes
87C	6	0.0	Lagunitas Campground	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion occuring on severnal portions of the road going to upper campground	2	yes	sediment attributed to Rio San Antonio and Lagunita Lakes	2	yes	Fisheries conflict with sediment to Lagunita Lakes Fisheries and Big game summer habitat	2	access to lower campground	1	7	yes
87DD	6	0.2	Lagunitas Campground	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion occuring on severnal portions of the road	1	yes	sediment attributed to Rio San Antonio and Lagunita Lakes	1	yes	Fisheries conflict with sediment to Lagunita Lakes Fisheries and Big game summer habitat	1	Campground access	1	4	no
87E	6	0.0	Lagunitas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion occuring on severnal portions of road leading to the grant.	2	yes	sediment attributed to Rio Brazos on the Grant	2	none	big game summer habitat	2	access to grant private property	1	7	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
87F	6	0.5	Lagunitas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion occurring on several portions of road leading to the grant.	2	yes	sediment attributed to Rio Brazos on the Grant	2	none	no limitations in seasonal use at this time big game summer habitat	1	access to grant private property	1	6	no
87H	6	0.1	Osier	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion occurring on portions of road that goes through meadows. Portion of this road is closed to discouraged travel due to watershed issues	3	yes	sediment attributed to Osier Fork of Rio Brazos	2		no limitations in seasonal use at this time. Sediment to fisheries big game summer habitat. Fisheries concerns	1	access to grant private property, CDT crosses portion of road	1	7	yes
87H1A	6	0.2	Osier	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	none noted	1	none that we are familiar with	this portion of road is a re-alignment to prevent motorized travel through a wet meadow.	1	none	no limitations in seasonal use at this time big game summer habitat	1	road re-alignment section	1	4	no
87M	6	0.4	Osier	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	none noted	1	none that we are familiar with	none	1	none	no limitations in seasonal use at this time big game summer habitat	1	small road to top of a rocky hill	1	4	no
87S	6	0.3	Lagunitas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector	Native	yes	erosion occurring on several portions of road leading to the grant.	2	yes	sediment attributed to Rio Brazos on the Grant	2	none	no limitations in seasonal use at this time big game summer habitat	1	access to grant private property	1	6	no
87T	6		Oso Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion occurring on portions of road	2	none that we are familiar with	none	1	none	no limitations in seasonal use at this time big game summer habitat	1	dispersed camping, hunting access. Use by livestock permittees for base camp	1	5	yes
87T1	6	0.1	Oso Spring	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	meadow area	1	none noted	none noted	1	none	no limitations in seasonal use at this time big game summer habitat	1	dispersed camping, hunting access. Use by livestock permittees for base camp	1	4	yes
87V	6	0.0	Banco Julian	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion occurring on portions of road. Road goes through open meadow to overlook	2	none that we are familiar with	none	1	none	no limitations in seasonal use at this time big game summer habitat	1	dispersed camping and hunting use. Used by livestock permittees	1	5	yes
87V1	6	0.2	Banco Julian	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	not found	none	1	none	none	1	none	none	1	closed road	1	4	no
87W	6	0.3	Lagunitas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Collector	Native	yes	erosion occurring on portion of short road	2	none that we are familiar with	none	1	none	none	1	not sure what road is used for	1	5	no
87X	6	1.1	Lagunitas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector	Native	yes	erosion occurring on portion of short road steep slope to river	1	yes	steep slope erosion	2	none	none	1	dispersed camping until existing berm some unrestricted motorized travel	1	5	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
88A	6	0.7	Nutritas/Poorbough	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion	1	yes	adjacent to Rio san Antonio sediment directly to San Antonio	3	yes	fisheries TES fish	3	access to private land	1	8	no
91	6	8.8	Tusas Mountain	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	some graveled to about Rinker Lake native surface Rinker lake to 91b	1	yes	wet meadows braided road, user created roads to cross	2	none	big game habitat	2	dispersed camping invasive plants established	1	6	yes
9103	6	0.9	Rinker Lake/Turkey Lake	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	when wet ruts, slippery when wet, poor condition	1	yes	when wet ruts, slippery when wet, poor condition	2	none	big game habitat	2	dispersed camping abandoned mines are adjacent, CDT. A section of 91c3 is suggested as new road approx. 1/4 from Rinker Lake.	1	6	no
91A	6	2.5	Cow Creek	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	when wet ruts, slippery when wet, poor condition	1	yes	when wet ruts, slippery when wet, poor condition	2	none	big game habitat	2	access to acequia and to private lands	1	6	no
91B	6	12.2	Spring Creek/Hopewell	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	Collector	Native	yes	poor road conditions when wet	2	yes	cross country travel by ATVs	3	none	big game habitat	2	invasives along road, access to private lands, heavily used by recreationists	1	8	yes
91B1	6	3.0	Hopewell Lake	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	steep slope erosion occurring,	2.00	yes	steep slope erosion occurring,	2	yes	fish brookies suckers	2	access to gold panning, CDT segment, crosses Placer creek	1	7	no
91B31	6	1.6	Rock Creek	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	poor road conditions when wet	2	none	none	1	none	none	1	closed and reopened graded access to private lands	1	5	no
91BC	6	0.7	Cleveland Gulch	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion and funnelwater into the creek	2	yes	adjacent to the creek, was fishery in 1930's creek is intermittent with surface flow	3	yes	user created roads come off this road		closed abandoned mines some sealed	1	6	no
91C3	6	1.1	Rinker Lake/Turkey Lake	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	spur road off 91 braided road	2	yes	spur road off 91 braided road	1	yes	wet meadow culverts to permit water flow	2	dispersed camping access to tanks access to Burnt Mountain	1	6	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
91CC	6	1.1	Tusas Mountain/Gravel Pit road	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	gravel pit erosion along the road rocky road	2	none noted	rocky little erosion	1	yes	big game habitat	2	access to garavel pit	1	6	no
93	6	9.0	Nutritas	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion slippery places when when crosses unprotected drainage shawcroft corral	3	yes	crosses 3 drainages, trailing and herding cattle, potential hardening needed	3	yes	fisheries TES fish	3	access to private lands access to the grant cultural resource concerns	1	10	yes
93B	6	1.0	Nutritas	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	wet meadows crossed	3	yes	wet meadows crossed	2	yes	fisheries TES fish big game habitat	3	follows the land grant from 93 to US 64 access to Jawbone area CDT cultural resosource concerns 64B	1	9	no
93C	6	0.1	Warm Springs/Nutritas creek	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	small spur off of 93 erosion slippery places when when crosses unprotected drainag	2	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	none	none noted	1	dispersed camping, ATV use	1	5	no
96B	6	0.3	Drake ranch	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	fuelwood, ATV use, dispersed camping, Pinyon picking, private land access	1	6	yes
96B1	6	0.1	Carson area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	fuelwood, ATV use, dispersed camping, Pinyon picking,	1	6	yes
96C	6	0.2	Taos Junction	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	fuelwood, ATV use, dispersed camping, Pinyon picking,	1	6	yes
96C1	6	0.2	Taos Junction/Carson	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	fuelwood, ATV use, dispersed camping, Pinyon picking,	1	6	no
96Y	6	0.2	Drake ranch	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	fuelwood, ATV use, dispersed camping, Pinyon picking,	1	6	no
97	6	9.3	Commanche/Servilleta	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Collector	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter habitat seasonal closure connects into D_2	2	dispersed camping, fuelwood, , pinyon picking	1	6	yes
97B	6	0.2	Owl Tank/Servilleta	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	dispersed camping, fuelwood, , pinyon picking	1	6	no

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES				
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
97B1	6	0.1	Servilleta area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	dispersed camping, fuelwood, , pinyon picking	1	6	no
97B2	6	0.2	Servilleta area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	dispersed camping, fuelwood, , pinyon picking	1	6	no
97B3	6	0.3	Servilleta area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	dispersed camping, fuelwood, , pinyon picking	1	6	no
97B4	6	0.3	Servilleta area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	dispersed camping, fuelwood, , pinyon picking	1	6	no
97B4	6	0.6	Servilleta area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	dispersed camping, fuelwood, , pinyon picking	1	6	no
97B5	6	0.2	Servilleta area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	dispersed camping, fuelwood, , pinyon picking	1	6	no
A14	6	0.4	Comanche Rim	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	fuelwood gathering, hunting	1	6	no
A15	6	0.2	Comanche Rim	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	fuelwood gathering, hunting	1	6	no
A17	6	0.0	Taos Junction	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, rocky near rim	1	none noted	none noted	1	yes	winter big game habitat	2	fuelwood gathering, hunting	1	5	no
A22	6	0.0	TCLP	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	fuelwood gathering, hunting	1	6	no
A27	6	0.7	TCLP	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	fuelwood gathering, hunting	1	6	no
A28	6	0.2	TCLP	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	fuelwood gathering, hunting	1	6	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
A32	6	0.6	Servilleta area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	fuelwood gathering, hunting	1	6	no
A33	6	0.5	Servilleta area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	fuelwood gathering, hunting	1	6	no
A34	6	0.2	Servilleta area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	fuelwood gathering, hunting	1	6	no
A39	6	0.0	Servilleta area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	winter big game habitat	2	fuelwood gathering, hunting	1	6	no
A43	6	0.2	Servilleta area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	winter habitat	2	yes	winter big game habitat	2	fuelwood gathering, hunting	1	6	no
B19	6	0.5	Burned Mountain	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none	see wildlife comments	3	yes	spur road off 91B braided road	2	yes	wet meadow culverts to permit water flow	2	dispersed camping access to Moeller Spring area, ATV use	1	8	no
B20	6	1.3	Burned Mountain	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none	see wildlife comments	3	yes	spur road off 91B braided road	2	yes	wet meadow culverts to permit water flow	2	dispersed camping access to tanks goes away from Moeller Spring, ATV use, North of 91B	1	8	no
B31	6	0.6	goes to private land off FR 133 south end of PVT	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	soil erosion	2	yes	sediment to Little Tusas	2	yes	Fisheries, Big Game Habitat	2	Access to private land,	1	7	no
C13	6	0.9	Mule Canyon	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	soil erosion minimal, gets muddy	2	yes	Sediment to private and disperses out	2	yes	Wildlife use from biggame	1	access to Price Smith tank	1	6	no
C16	6	0.6	Mule Canyon	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	soil erosion present	2	yes	Sediment to FR 576	1	yes	Wildlife use from biggame	1	access to Allotment boundaries	1	5	no
E10	6	0.1	Tio Gordito/Amador/L Tank	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Deep loamy soil, erodable soils present	2	yes	sediment load to Aguaje	2	yes	Big Game habitat	2	used by Carson residents, adjacent to Subdivision	1	7	no

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
E16	6	1.0	Tio Gordito/Amador/L Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	drains on road	2	yes	sediment to South Amador tank	2	yes	Big Game habitat and Turkey	2	dispersed camping, hunting use, fuelwood gathering	1	7	no
E23	6	0.2	Tio Gordito/Amador/L Tank	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	drains on road	2	yes	sediment to old well tank	2	yes	Big Game habitat and Turkey	2	dispersed camping, hunting use, fuelwood gathering, pinon picking	1	7	no
E27	6	0.1	Tio Gordito/Amador/L Tank	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	drains on road, erosion on road	2	yes	sediment to tio Gordito Arroyo	2	yes	Big Game habitat and Turkey	2	dispersed camping, hunting use, fuelwood gathering, pinon picking	1	7	no
F3	6	0.3	Tio Gordito/Amador/L Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	rocky conditions	1	none noted	rocky little erosion	1	yes	Big Game habitat and Turkey	2	dispersed camping, hunting use, fuelwood gathering, pinon picking	1	5	no
F7	6	0.2	Tio Gordito/Amador/L Tank	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	too small	1	none noted	no sediment delivery	1	yes	Big Game habitat and Turkey	2	dispersed camping, hunting use, fuelwood gathering, pinon picking	1	5	no
G2	6	0.7	Hopewell Lake	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	slight erosion	2	yes	drainage into Long Canyon into wet meadow	2	yes	Big Game Habitat	2	dispersed camping, hunting, livestock driveway from pvt to corral-historical	1	7	no
H10	6	0.3	Laguna Larga	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	Gully erosion near contributing to sediment delivery to Rio de los Pinos	3	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting,	1	8	no
H11	6	1.2	Laguna Larga	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	Gully erosion near contributing to sediment delivery to Rio de los Pinos	3	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting,	1	8	no
H12	6	0.7	Pinebatal Mesa	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	no sediment delivery	1	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting,	1	6	no
H13	6	0.3	Laguna Larga/Chino Lake	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	Gully erosion near contributing to sediment delivery to Rio de los Pinos	3	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting,	1	8	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
H14	6	0.3	Laguna Larga/Chino Lake	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	Gully erosion near contributing to sediment delivery to Rio de los Pinos	3	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting,	1	8	no
H15	6	0.3	Laguna Larga/Chino Lake	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	Gully erosion near contributing to sediment delivery to Rio de los Pinos	3	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting,	1	8	no
H16	6	0.5	Laguna Larga/Chino Lake	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	Gully erosion near contributing to sediment delivery to Rio de los Pinos	3	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting,	1	8	no
I10	6	0.0	San Antonio Mntn	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	none noted	1	none noted	none noted	1	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	un-authorize motorized travel to San Antonio Mt.	1	5	no
I11	6	0.7	San Antonio Mntn	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	none noted	1	none noted	none noted	1	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	un-authorize motorized travel to San Antonio Mt.	1	5	no
I14	6	0.4	Laguna Larga	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	Gully erosion near contributing to sediment delivery to Rio San Antonio	3	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting,	1	8	no
I15	6	1.1	Laguna Larga	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	Gully erosion near contributing to sediment delivery to Rio San Antonio	3	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting,	1	8	no
I16	6	1.2	Laguna Larga	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	erosion on road, channels water down road. Rutted road. Road re-routed in some areas at bad spots. Primitive road, rocky	2	yes	Gully erosion near contributing to sediment delivery to Rio San Antonio	3	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	livestock permittee use, dispersed camping, hunting,	1	8	no
I17	6	0.1	San Antonio Mntn	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	none noted	none rocky	1	none noted	none noted	1	yes	no limitations in seasonal use at this time big game wintering habitat and migration corridors	2	un-authorize motorized travel to San Antonio Mt.	1	5	no
J12	6	0.6	Banco Julian	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	some erosion occurring on part road	1	none noted	none noted	1	yes	big game habitat	2	dispersed camping, unauthorized motor travel, hunting use,	1	5	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
J35	6	1.9	Cisneros Park	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	soil erosion occurs on sloped road, and goes through the drainages and meadow	2	yes	sediment delivery to Little Tusas	2	yes	big game habitat fisheries into Rio Tusas TES	3	dispersed camping, fuelwood gathering, forest product gathering, hunting	1	8	no
J37	6	1.1	Cisneros Park	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	soil erosion on road,	1	yes	sediment delivery to Little Tusas	2	yes	big game habitat fisheries into Rio Tusas TES	3	dispersed camping, fuelwood gathering, forest product gathering, hunting	1	7	no
K12	6	0.8	Sublette	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	some soil movement from road to sagebrush flats	2	yes	road drains fairly well, road is gravelly	2	yes	big game habitat	2	dispersed camping, hunting. Area hunted primarily by Colorado residents	1	7	no
K13	6	1.4	Oso Spring	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	road contributes to sediment delivery to the drainage bottom	2	yes	It is a closed road part of a past timber sale within the Oso Spring area	2	yes	big game habitat	2	Area adjacent to the road is used heavily as dispersed camping along with hunting activities	1	7	no
K17	6	0.6	Sublette	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	Spur road of FR 75. Contributes to Sediment delivery to Canyon Atencio. Road does not have any purpose	2	yes	Road acts as a drainage system to FR 75 at both ends.	2	yes	Area hunted primarily by Colorado residents big game habitat	2	Spur road connects to FR 75 and FR 494 It is a small portion or road used primarily by ATVs and high clearance vehicles with little to no purpose.	1	7	no
P10	6	0.1	TCLP Noria Area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dustry, wet may be impassible, ruts and slippery when wet	1	yes	dry dustry, wet may be impassible, ruts and slippery when wet	2	yes	big game winter habitat	2	access to and from private to forest	1	6	no
P13	6	0.4	TCLP Noria Area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dustry, wet may be impassible, ruts and slippery when wet	1	yes	dry dustry, wet may be impassible, ruts and slippery when wet	2	yes	big game winter habitat	2	spur road access to pvt land	1	6	no
P14	6	0.4	TCLP Noria Area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dustry, wet may be impassible, ruts and slippery when wet	1	yes	dry dustry, wet may be impassible, ruts and slippery when wet	2	yes	big game winter habitat	2	private land forest service access issues, not clear on special use permit for easment	1	6	no
P15	6	0.5	TCLP Noria Area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dustry, wet may be impassible, ruts and slippery when wet	1	yes	dry dustry, wet may be impassible, ruts and slippery when wet	2	yes	big game winter habitat	2	private land forest service access issues, not clear on special use permit for easment	1	6	no
P17	6	0.2	TCLP Noria Area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dustry, wet may be impassible, ruts and slippery when wet	1	yes	dry dustry, wet may be impassible, ruts and slippery when wet	2	yes	big game winter habitat	2	spur road off of FR 556	1	6	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
P18	6	0.7	Drake ranch	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	big game winter habitat	2	South of Drake Ranch	1	6	no
P20	6	0.4	Drake ranch/Harting Tank	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	big game habitat	2	South of Drake Ranch	1	6	no
P21	6	0.4	Drake ranch	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	big game habitat	2	Connect 96B and 96C	1	6	no
P23	6	0.7	Drake ranch	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	big game habitat	2	South of Drake Ranch	1	6	no
P26	6	0.5	Drake ranch	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	big game habitat	2	South of Drake Ranch	1	6	no
R15	6	1.8	Ojo Caliente/Sandlin Arroyo	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	dry dusty, wet may be impassible, ruts and slippery when wet	1	yes	dry dusty, wet may be impassible, ruts and slippery when wet	2	yes	big game habitat	2	fuelwood gathering, hunting access pinon gathering	1	6	no
R16	6	1.0	Mesa Vibora	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soil very erodable near arroyos	2	yes	erosion occuring near and adjacent arroyos	2	yes	big game habitat	2	fuelwood gathering, hunting access pinon gathering	1	7	yes
R21	6	0.3	Commanche	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soil very erodable near arroyos	2	yes	erosion occuring near and adjacent arroyos	2	yes	big game habitat	2	fuelwood gathering, hunting access pinon gathering	1	7	no
R22	6	0.3	Commanche	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soil very erodable near arroyos	2	yes	erosion occuring near and adjacent arroyos	2	yes	big game habitat	2	fuelwood gathering, hunting access pinon gathering	1	7	no
R24	6	0.4	Taos Junction	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soil very erodable near arroyos	2	yes	erosion occuring near and adjacent arroyos	2	yes	big game habitat	2	fuelwood gathering, hunting access pinon gathering	1	7	no
R26	6	0.6	Sandlin Arroyo/Ojo Caliente	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Collector	Native	yes	sandy soil very erodable near arroyos	2	yes	erosion occuring near and adjacent arroyos	2	yes	big game habitat	2	fuelwood gathering, hunting access pinon gathering	1	7	no

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
R27	6	1.4	Sandlin Corral	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soil very erodable near arroyos	2	yes	erosion occurring near and adjacent arroyos	2	yes	big game habitat	2	fuelwood gathering, hunting access pinon gathering	1	7	no
R28	6	0.4	Sandlin Area	1 - BASIC CUSTODIAL CARE (CLOSED)	2 - HIGH CLEARANCE VEHICLES	Local	Native	yes	sandy soil very erodable near arroyos	2	yes	erosion occurring near and adjacent arroyos	2	yes	big game habitat	2	fuelwood gathering, hunting access pinon gathering	1	7	no
7	7	5.9	DH Lawrence Ranch	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	COLLECTOR	AGG - CRUSHED AGGREGATE OR GRAVEL	no	none noted	1	NONE NOTED	none noted	1	no	none noted	1	Access to private lands, heritage resource sites nearby county maintains part also access to wilderness study area	2	5	Yes
9	7	3.5	Cebolla mesa	3 - SUITABLE FOR PASSENGER CARS	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sediment from lack of more regular maintenance	2	yes	winter range deer & elk	2	firewood, hunting, access to campground & trail to river	1	7	Yes
54	7	1.7	Jiron Canyon to Laguna Saddle/FR134	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	lack of drainage, big mud holes, silty	2	YES	sedimentation into Jiron	2	no	none noted	1	jeep trails high clearance	1	6	Yes
58	7	1.3	West Fork road	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	Yes	no fines, loose shale	1	YES	adjacent to stream, lacks buffer zones in places, springs in road	2	Yes	fisheries, beaver	2	Provides access to middle fork lake road & private land, angler & camping uses	2	7	Yes
77	7	3.0	Bitter Creek	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	LOCAL	NAT - NATIVE MATERIAL	yes	hydrothermic soils washing into Bitter Crek	2	YES	hydrothermic soils washing into Bitter Creek	2	no	none noted	1	Access to private lands	1	6	No
132	7	4.0	Telephone line road/lama high road. Continues thru private land to south and connects to 493B	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	erosive clay, deeply rutted	2	YES	North end blown out from Hondo fire.	2		none noted	1	none	1	6	Yes
134	7	14.7	Cabresto road	4 - SUITABLE FOR PASSENGER CARS. MODERATE DEGREE OF USER COMFORT	3 - SUITABLE FOR PASSENGER CARS	COLLECTOR	AGG - CRUSHED AGGREGATE OR GRAVEL	no	none noted	1	YES	proximity to stream	2	Possible	tes fisheries add cloosure to add 15 days to be consistent with Valle Vidal, jeep tours depend on june 15 date to access midnight meadows	3	livestock driveway	1	7	Yes

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES				
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
195	7	15.7	Elephant Rock	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	hydrothermic soils soils prone to movement when water allowed to penetrate deeply	2	NONE NOTED	none noted	1	none	none noted	1	motorcycle trail NEPA process done	1	5	No
480	7	0.5	Old Red River Pass road	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	steep switchbacks, sloughing sidelopes	2	NONE NOTED	little to no drainage	2	No	none noted	1	Historical road, road used by ranch owner year round,private landowner plows snow	2	7	Yes
482	7	2.3	Cebolla Mesa, delete, same as 9709RO	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	Possible	bearing strength	1	NONE NOTED	none noted	1	none	none noted	1	seasonal closure	1	4	No
485	7	4.6	Pioneer Creek	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	Yes	Steep road, established during mining era, poor location	1	Possible	Steep slopes, Adjacent to Pioneer Creek	2	Possible	Fisheries	2	popular OHV route, dispersed camping, mine features and potential for mine tours. Town water well and storage tank.	2	7	Yes
486	7	7.0	Placer Creek to Goose lake	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	Steep road, established during mining era, poor location	2	NONE NOTED	none noted	1	none	none noted	1	popular OHV route, access to Goose Lake.	2	6	Yes
487	7	2.0	Middle Fork Lake	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	high elevations steep slopes,tight switchbacks due to lack of drainage loss up to 8 feet of soil, deeply incised	2	YES	lack of maintenance causes sediment into Red River, water quality, two road crossing	2	yes	fisheries	2	access to Lake, safety issue on road, maintainence difficult	2	8	No
488	7	2.1	continuation of Old Red River Pass road to SH 38	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	Yes	sandy soils, not enough maintenance, low bearing strength in places, rutted	1	NONE NOTED	none noted	1	no	none noted	1	access to EFXC. Would make good mtn. Bike trail.	2	5	No
490	7	3.2	Foster Park/4th of July Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	deeply rutted, steep sections	2	YES	crosses head of several tributaries, Proximity to stream in 4th of July	2	no but possible on 4th of July Canyon	fisheries in 4th of July	2	popular challenging 4 wheel drive road, motorcycles, ATV's loop w/ Old RR Pass, Foster park	2	8	Yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
491	7	3.0	Exploration Road	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	very rocky at bottom. Crosses hydrothermic scar at top, debris fields in sec 19	2	YES	lack of maintenance erosion into Malette Creek	2	yes	allows access to Midnight Meadows during elk calving	2	seasonal closures	1	7	No
493	7	10.2	San Cristobal/lama highway	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	COLLECTOR	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	NONE NOTED	none noted	1	No	none noted	1	residential access, Taos Pueblo access to clay source	2	6	Yes
597	7	8.8	Malette Sawmill	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	ARTERIAL	AGG - CRUSHED AGGREGATE OR GRAVEL	no	none noted	1	NONE NOTED	none noted	1	no	none noted	1	private land access	1	4	Yes
1900	7	3.5	Costilla Reservoir road	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	COLLECTOR	AGG - CRUSHED AGGREGATE OR GRAVEL	No	none noted	1	YES	Parts of road adjacent to the creek. Buffer zones exist along most of road	2	Yes	heavy elk use of area, gate exists on road possible closure tes project access fisheries	2	Invasive plants along the road	2	7	Yes
1905	7	0.4	Gold Creek	1 - BASIC CUSTODIAL CARE (CLOSED TO MOTOR VEHICLE TRAFFIC)	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	No	none noted	1	YES	Adjacent to comache Creek and Gold Creek	2	Yes	Sediment to Comanche Creek	2	access Clayton cabin, upper Comanche Creek, Valle Vidal area	1	6	Yes
1910	7	5.5	West side loop road Valle Vidal	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	COLLECTOR	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	On southern end of road near Ponil Creek waters	2	No	none noted	1	Invasive plants along the road	2	7	Yes
1913	7	7.4	9 mile road	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	NONE NOTED	none noted	1	Yes	Access upper end of Greenwood Canyon,	1	Road contains many rough areas, has potential for vista destination points	1	5	Yes
1914	7	8	Loop road east	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	COLLECTOR	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	Adjacent to Sealy canyon on upper portion of road	2	Yes	winter elk habitat, wildlife security area in winter	2	gates close road during winter period limiting access	1	7	Yes
1915	7	0.7	Lookout Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	No	none noted	1	NONE NOTED	none noted	1	No	none noted	1	access to Vermejo ranch properties. Short section of road. Old white gate area	2	5	Yes
1950	7	27.4	Valle Vidal cross road	4 - SUITABLE FOR PASSENGER CARS, MODERATE DEGREE OF USER COMFORT	4 - SUITABLE FOR PASSENGER CARS, MODERATE DEGREE OF USER COMFORT	ARTERIAL	AGG - CRUSHED AGGREGATE OR GRAVEL	No	none noted	1	YES	adjacent to Costilla Creek and Comanche Creek road is surfaced	2	Yes	Increase vehicle traffic through the Valle Vidal fisheries tes project future	3	Contains scenic vistas, access route for visitors to area Invasive plants along the road some logging on private land uses this road	2	8	Yes

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria	Sum of Criteria	Min road system
97012	7	1.7	Penasquito/Pinebehta	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	road in drainage bottom	2	no	none noted	1	access to Latir Peak wilderness private mine	2	7	No
132A	7	0.7	connects high road to private block. Lama	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	erosive clay, deeply rutted seasonal closure due to frost leaving road	2	YES	steep, rutted	2	none	none noted	1	none	1	6	No
134A	7	1.9	Cabresto Lake	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	no	none noted		YES	steep road, proximity to stream, switch-back cutting	2		none noted	1	none	1	5	Yes
1914A	7	0.1	Beatty Lake parking area	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	No	none noted		NONE NOTED	none noted	1	No	none noted	1	access to Beatty Lakes	2	5	No
493A	7	1.0	San Cristobal community	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	P - PAVED	no	none noted		NONE NOTED	none noted	1	no	none noted	1	residential access, Taos Pueblo access to clay source	2	5	Yes
493B	7	1.8	San Cristobal east	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL, graveled section near top	no	none noted		NONE NOTED	none noted	1	no	none noted	1	private land access	2	5	Yes
493C	7	1.6	San Cristobal east	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	erosive clay, deeply rutted	2	YES	from Hondo fire, road goes straight up hill	1	no	none noted	1	access to San Cristobal canyon by range permittees & hikers trail head, trailhead in San Cristobal	2	6	Yes
54B	7	1.2	access to Sanchez property from Laguna Saddle/FR134	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	no	none noted		YES	off road trespass into wet meadows	2	no	none noted	1	none	1	5	Yes
54C	7	1.9	from Laguna saddle west of Bitter Creek, through town of Midnight	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	erosion, gullies, puddles. Lack of maintenance	3	YES	sediment into Bitter Creek	2	no	none noted	1	illegal access to exploration road	2	8	Yes
54D	7	1.3	Greenie Peak	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	braded, steep section to Peak,		YES	Jiron crossing/ off road trespass	2	no	none noted	1	none	1	5	Yes
54E	7	0.8	Anchor Mine cabin	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	deeply rutted, steep sections	2	YES	watershed crossing	2	yes	RG cutthroat in Bitter Creek	2	illegal access to Anchor/Eddison mines & on into V.V... Jeep tour destination	2	8	Yes

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES			Sum of Criteria	Min road system
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
54F	7	1.3	Midnight Mine	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	deeply rutted, steep sections	2	YES	sediment into Malette	2	yes	spring elk calving in meadows	2	illegal access to private land and Anderson Park	2	8	Yes
54G	7	0.6	Anderson Park	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	rutted road, pot holes. Lack of drainage	2	NONE NOTED	none noted	1	no	none noted	1	illegal public access to Anderson Park. Access to Warming hut	2	6	Yes
54H	7	4.1	Jiron Canyon to 54K. Main stem of Trail Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	no	none noted	1	NONE NOTED	none noted	1	no	none noted	1	none	1	4	Yes
54I	7	1.9	Jiron to FR134	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	closed road, revegetating	1	NONE NOTED	none noted	1	no	none noted	1	none	1	4	Yes
54J	7	2.4	Trail Canyon to Bonito Canyon system	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	steep, rutted, rocky	2	YES	sediment into Bonito	2	no	none noted	1	none noted	1	6	Yes
54J1	7	2.7	Bonito Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	steep, rutted, rocky	2	YES	sediment into Bonito	2	no	none noted	1	none noted	1	6	Yes
54J2	7	1.9	Greenie Peak/Malette	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	steep, rutted, rocky	2	YES	sediment into Bonito	2	no	none noted	1	none noted	1	6	Yes
54K	7	2.6	Lower segment of Trail Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	no	none noted	1	NONE NOTED	none noted	1	no	none noted	1	none noted	1	4	Yes
54K1	7	2.0	alt. trail canyon route	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	steep, rutted, rocky	2	YES	sediment into Bonito	2	no	none noted	1	none noted	1	6	Yes
54K2	7	0.7	alt. trail canyon route	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	steep, rutted, rocky	2	YES	sediment into Bonito	2	no	none noted	1	none noted	1	6	Yes
54K3	7	0.6	alt. trail canyon route	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	steep, rutted, rocky	2	YES	sediment into Bonito	2	no	none noted	1	none noted	1	6	Yes
54K4	7	0.4	alt. trail canyon route	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	steep, rutted, rocky	2	YES	sediment into Bonito	2	no	none noted	1	none noted	1	6	Yes
54K5	7	0.4	alt. trail canyon route	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	steep, rutted, rocky	2	YES	sediment into Bonito	2	no	none noted	1	none noted	1	6	Yes

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system	
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts			Criteria
58A	7	1.1	Ditch Cabin/East Fork	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	sandy soils, not enough maintenance	2	YES	too close to stream	2	yes	fisheries	2	access to wilderness trailhead & parking	2	8	Yes
597A	7	0.8	golf course to Gallagher Ranch road	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	Yes	silty, rutted	2	YES	proximity to stream, water crossings	2	no	none noted	1	access to private land	2	7	Yes
6A	7	0.2	Eagle rock Lake parking	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	LOCAL	IMP - IMPROVED NATIVE MATERIAL	no	none noted	1	NONE NOTED	none noted	1	no	none noted	1	Access to Eagle Rock Lake	2	5	Yes
6E	7	0.6	Columbine Campground	5 - SUITABLE FOR PASSENGER CARS, HIGH DEGREE OF USER COMFORT	5 - SUITABLE FOR PASSENGER CARS, HIGH DEGREE OF USER COMFORT	LOCAL	P - PAVED	No	none noted	1	NONE NOTED	none noted	1	no	none noted	1	none noted	1	4	Yes
705X	7	1.2	Cebolla Mesa treatment plant	3 - SUITABLE FOR PASSENGER CARS	3 - SUITABLE FOR PASSENGER CARS	LOCAL	AGG - CRUSHED AGGREGATE OR GRAVEL	no	none noted	1	NONE NOTED	none noted	1	no	none noted	1	none noted	1	4	Yes
7A	7	\$2.0	loop between 7 and 7C, San Cristobol	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	TEU 159 & 143, erosive	2	YES	road below grade, water collects on road during runoff	2	yes	deer poaching	2	access to range improvements, access to pipeline	2	8	Yes with reservations
7C	7	\$3.1	Arroyo Hondo	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	TEU 159 & 143, erosive	2	YES	road below grade, water collects on road during runoff	2	yes	deer poaching	2	access to range improvements, access to pipeline	2	8	Yes
7C1	7	\$0.7	Cerro Negro	2 - HIGH CLEARANCE VEHICLES	1 - BASIC CUSTODIAL CARE (CLOSED TO MOTOR VEHICLE TRAFFIC)	LOCAL	NAT - NATIVE MATERIAL	Yes	Poor location, steep slopes	2	Possible	poor location, steep slopes	2	yes	deer poaching	2	Dead end road, recreational hunting, cultural resource concerns	2	8	No
9701A	7	\$3.3	El Rito/Latir/ Primero Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	crossed by several small side streams	2	yes	protection of critical habitat/winter range deer & elk	2	access to stream for acequia, access to popular climbing site	2	8	No
9709R0	7	1.8, check length change to same as 482?	Garrapata Canyon	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	proximity to stream	2	yes	winter range deer & elk	2	mineral permits sand	2	8	No
9A	7	1.5	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	firewood, hunting	1	7	No
9A1	7	1.1	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system	
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts			Criteria
9A2	7	0.6	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9A3	7	0.8	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9A4	7	6.1	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9A5	7	0.2	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9B	7	1.2	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9C	7	0.1	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9D	7	0.5	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9E	7	1.4	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9F	7	1.4	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9G	7	0.5	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9H	7	0.7	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9I	7	1.2	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9J	7	1.0	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9K	7	0.2	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9L	7	1.0	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9M	7	1.0	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9N	7	0.2	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9P	7	0.2	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9Q	7	0.8	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9R	7	0.9	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No

NFSR Number	District Number	Approximate length (mile)	ROAD				SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system	
			General Location	Objective Level	Maintenance level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts			Criteria
9S	7	0.4	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9T	7	1.4	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9U	7	2.3	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9V	7	0.6	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9W	7	1.2	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9X	7	0.8	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9Y	7	1.2	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
9Z	7	0.9	Cebolla Mesa	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	yes	clay soils, road quickly rutted	2	YES	sedimentation, ground cover loss, headcuts	2	yes	winter range deer & elk	2	none noted	1	7	No
Bull of Woods/ West Fork Red River	7	0.8	Bull of the Woods	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	ADMINISTRATIVE USE ONLY	NAT - NATIVE MATERIAL	no	none noted	1	YES	proximity to Rio Hondo	2	yes	big horn sheep	2	no public access from TSV	1	6	No
Cim. CG	7	0.7	Cimarron Campground	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	LOCAL	NAT - NATIVE MATERIAL	No	none noted	1	NONE NOTED		1	No	none noted	1	none noted	1	4	Yes
Largo	7	0.8	follow Largo Canyon to private	MOTORCYCLES	MOTORCYCLES	local loop	NAT - NATIVE MATERIAL	yes	steep, lack of maintenance, frequently washed out after Hondo fire	3	YES	proximity to stream	2	no	none noted	1	recreational use trail UDD road??	1	7	No
sawmill road from 597 to trail canyon system	7	1.7	part of trail canyon system	MOTORCYCLES	MOTORCYCLES	sawmill road from 597 to trail canyon system	NAT - NATIVE MATERIAL	no	none noted	1	NONE NOTED	none noted	1	no	none noted	1	staging for snowmobile users, easy bypass for lower segment of Trail Canyon	1	4	No
segment between Largo & 132.	7	0.8	avoid private lands in La Lama area	2 - HIGH CLEARANCE VEHICLES	2 - HIGH CLEARANCE VEHICLES	connect between Largo & high road, bypass to avoid private land to the south	NAT - NATIVE MATERIAL	yes	lack of maintenance, rutted	2	NONE NOTED	none noted	1	no	none noted	1	none noted	1	5	No
Tri. 171	7	2.4	Pioneer motorcycle loop east	MOTORCYCLES	MOTORCYCLES	TRAIL	NAT - NATIVE MATERIAL	yes	erosion trail stabilization	2	Possible	none noted	1	Possible	Pea clams, or other TES	3	recreational use trail	1	7	Yes with reservations - trail
Tri. 64	7	0.8	Pioneer motorcycle loop west	MOTORCYCLES	MOTORCYCLES	TRAIL	NAT - NATIVE MATERIAL	yes	erosion trail stabilization	2	Possible	High elevation, Deer Lake, Pioneer Creek	2	Possible	Pea clams, or other TES	3	start at end of 4 wheel drive road motorcycles using trail along with foot traffic and horses	1	8	Yes with reservations - trail

NFSR Number	District Number	Approximate length (mile)	ROAD					SOILS			WATERSHED			WILDLIFE			OTHER RESOURCES		Sum of Criteria	Min road system
			General Location	Objective Level	Maintainence level	Function	Surface	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Conflicts	Narrative	Criteria	Comments/conflicts	Criteria		
UD7-1223- from sr 38 to Elephant Rock motorcycle loop	7	0.4	road can be easily opened. Access from 493 to 132 on forestlands	1-CLOSED	1-CLOSED	make a level 2 assign number such as 132B seasonal restriction same as 132	NAT - NATIVE MATERIAL	Access to ppvt land, access for la lama fuelwood gathering	accept with seasonal closure as on 132	1	none noted	none noted	1	none noted	none noted	1	none noted	1	4	Yes
										1 = none noted, slight erosion hazard, no rutting			1= none noted			1= no special habitat designated		3= cultural resources impacts known, high concentration of users	1-4 = low resource impacts likely	Yes = road on minimum system resource impacts low
										2 = moderate rutting, moderate erosion hazard			2= possible conflicts			2= important wildlife habitat such as winter habitat		2=cultural resources known, multiple uses, moderate uses	5-8 = moderate resource impacts	no = road not needed for minimum system resource impacts low to high
										3 = severe rutting, slick, severe erosion hazard			3=conflicts noted			3=TES habitat		1=none noted	9-12 = high resources impacts	