



File Code: 2210/2230

Date: February 20, 2008

Route To: (File)

Subject: End of Season Allotment Summary
Pahsimeroi Allotment

To: File

1) Livestock Numbers

a. Permitted and Season of Use

Permittee	No. and Class	Permit Type	Season of Use	Head Months
Circle Pi Ranches	400 Cow/Calf	Term	6/06 – 9/28	1512
Bob Whitworth	274	Term	6/06 – 9/28	1036

b. Actual Use

Permittee	Actual Use	Head Months	Season of Use Billed
Circle Pi Ranches	400 Cow/Calf	6/06 – 9/28	1512
Bob Whitworth	274	6/06 – 9/28	1036

c. Non-Use-Personal Convenience NA Rationale:

d. Resource Protection NA Rationale:

2) Pasture Rotation

Pasture	Number	Season
Christian Gulch / Up and Low Road Units	674	6/6 7/1
Mahogany Uplands	674	7/2 – 7/31
Spring Hill Uplands	674	8/1 - 8/30
Spring Hill Flats	674	8/31 – 9/28



3) Improvements

a. Annual Maintenance completed Yes X No ___

b. Reconstruction Completed Yes X No ___

Improvement #	Improvement Name	Description of Work
220367	Christian Gulch WD	Installed screen on springbox at source, repair pipeline, reset first trough and add one more trough, water system to all trough worked.
220335	Twin Springs WD	Complete overhaul of system, springbox was reset and fence repaired around spring, two new troughs were installed (second, and the fourth along the lower road), reset first trough to south of spring, repaired pipeline where needed.
220358	Spring Hill WD	Twin springs system feeding five watering spots, pipeline was repaired, reset the spring box at site 2, build fence around spring 2, plumb and install floats on draw troughs, replaced and reset double tanks in the timber, installed new trough on the flat above pasture fence (unplumbed).
220359	Lower Spring Hill WD	Reset spring box, repaired pipeline to rise over the saddle.
220366	Mule Springs	Repair pipeline to first troughs. Unable to get water to trough on the end.
220350	Mud Springs WD	Reset the two spring boxes, repaired pipeline, rebuilt fence around spring, placed float in troughs, and reset five troughs.
221053	Lower Spring Hill Pond	Repaired pond.
221078	Tw Ponds	Dug out silted in pond
221060	Twin Spring Pond	Dug out silted pond.
220337	Buck Creek Ridge Pond	Dug out silted pond.
220336	Buck Creek Pond	Dug out silted pond.

?	Carlson Road Pond#1	Dug out silted pond.
?	Carlson Road Pond #2	Dug out silted pond.
220345	Spring Hill Pond	Dug out silted pond
221067	Spring Hill Pond	Dug out silted pond
221068	Spring Hill Pond	Dug out silted pond

4) Compliance Yes X No

a. Notice of Non-Compliance/Justification NA

5) Monitoring

a. EOY (Effectiveness) Mahogany Creek is the main riparian area and is closed to grazing. The riparian areas did meet stubble height of greater than four inches by the end of the growing season. The uplands also met standards and were under 50% utilization.

b. Long Term (Implementation): N/A

RANGE STAFF